BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934
Business Reg. No.: 201626438D
☎ 6744 0777 6744 2377

Estimate Quotation

Quotation No	Nov 002/2020
Date	26/11/2020
Vehicle No	SGR249A
Make / Model	Toyota Harrier

Vecon.

To: M/s Sompo Insurance Singapore Pte. Ltd
Address: 50 Raffles Place, #05-01/06,Singapore Land Tower, Singapore 048623

Qty	DESCRIPTION	UNIT	Amount
	Items		
1pc	rear bumper torn		$ 1,385.00
1pc	n/s bumper retainer		$ 87.00
1 set	rear bumper clip		$ 40.00
	1512		
	1134		
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		$ ~~400.00~~ 200
2	to putty and spray painting on affected area	400	$ ~~500.00~~ 200
3	anti rust		$ 50.00
		Subtotal:	$ 2,462.00

BEST SOLUTION AUTOCARE PTE LTD

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

A/S 26/11/20.
02 Days
total: 1534
n/s: 1.2K ✓