# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E  GST Reg. No. 20-0405911-H

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1128Z**

| Qty | Description of Parts | Condition | Estimate By Workshop ($) | Our Adjusted ($) |
|---|---|---|---|---|
| | **REPLACEMENT OF PARTS** | | | |
| 1 | PRIG4 PANEL SUB-ASSY FRON | TO REPAIR SEE LABOUR | 1,264.00 | - |
| 1 | PRIG4 PANEL SUB-ASSY RR D | BENT | 1,258.30 | 1,258.30 |
| 1 | PRIG4 PANEL SUB-ASSY QUAR | TO REPAIR SEE LABOUR | 836.70 | - |
| 1 | PRIG4 MLDG ASSY BODY ROCK | TO REPAIR SEE LABOUR | 576.00 | - |
| 1 | PRIG4 WHEEL DISC | TO REPAIR SEE LABOUR | 1,555.10 | - |
| | LESS 25% DISCOUNT | | -1,372.53 | -314.58 |
| | | | 4,117.57 | 943.72 |
| | **NETT ITEMS** | | | |
| 1 | (I40) FRT DOOR LOGO CTPL (N) | NECESSARY | 75.00 | 75.00 |
| 1 | APP LOGO REAR DOOR L/R CT (N) | NECESSARY | 80.00 | 80.00 |
| | LESS 10% DISCOUNT | | -15.50 | -15.50 |
| | | | 139.50 | 139.50 |
| | **LABOUR** | | | |
| | PANEL BEATING (REPAIR RR BUMPER). INCLUSIVE OF THE REPAIR OF PRIG4 PANEL SUB-ASSY FRON, PRIG4 PANEL SUB-ASSY QUAR, PRIG4 MLDG ASSY BODY ROCK AND PRIG4 WHEEL DISC. | | 960.00 | 800.00 |
| | SPRAYPAINT ON AFFECTED AREA. | | 1,000.00 | 900.00 |
| | TUFF COAT ON AFFECTED PARTS. | | 50.00 | 30.00 |
| | TRANSFER OF DOOR FRT RH. | NOT NECESSARY | 120.00 | - |
| | TRANSFER OF DOOR REAR RH. | | 120.00 | 60.00 |
| | REMOVE / REFIX REVERSE SENSOR. | | 80.00 | 30.00 |
| | ADJUST REAR WHEEL ALIGNMENT. | | 80.00 | 80.00 |
| | | | 2,410.00 | 1,900.00 |
| | **GRAND TOTAL** | | **6,667.07** | **2,983.22** |

Report Ref No. NS/INC20013264/T1vf3e2

| RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | 2,983.22 |
|---|---|---|---|

Report Ref No. NS/INC20013264/T1vf3e2

**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**