LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2102734

INV Date 19/04/2021

Reference CC4/FCI21000178/Ara3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 1437Y

Insured Veh. SH 9660T

Claim No. D21000079MFSH

Policy No. D-20094922MFSH

Accident Date 31/12/2020

Inspection Date 05/01/2021

Description	**Total**
Third Party Express Settlement	500.00
Subtotal	**500.00**
GST (7%)	**35.00**
Grand Total	**535.00**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI21000178/Ara3q2
Date: 19/04/2021
Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9660T	**Veh. Inspected**	SMC 1437Y
Policy No.	D-20094922MFSH	**Coverage ($)**	0.00
Claim No.	D21000079MFSH	**Excess ($)**	0.00
Assign From	VIC	**Assign Date**	05/01/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN NOTE	**c.c**	1198
Engine No.	HIDDEN	**Year of Reg.**	2018
Chassis No.	JN1TAAE12Z0980582	**Colour**	GREY
Odometer	26864 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/12/2020	**Inspection Date**	05/01/2021
Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1437Y

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (N)	BUCKLED	847.80	847.80
2	FRONT BONNET HINGE @$35.00 (N)	NOT NECESSARY	70.00	-
2	FRONT HEADLAMP @$1614.60 (N)	CRACKED	3,229.20	3,229.20
2	FRONT HEADLAMP LOWER BRACKET @$28.10 (N)	NOT NECESSARY	56.20	-
1	FRONT GRILLE (N)	CRACKED	276.70	276.70
1	FRONT GRILLE EMBLEM LOGO (N)	NECESSARY	29.10	29.10
1	FRONT GRILLE TOP COVER (N)	CRACKED	194.40	194.40
1	FRONT GRILLE LOWER CHROME (N)	CUT	180.00	180.00
1	FRONT GRILLE LOWER GARNISH (N)	NOT NECESSARY	155.00	-
1	FRONT BUMPER (N)	DISTORTED	394.30	394.30
2	FRONT BUMPER SIDE RETAINER @$35.20 (N)	NECESSARY	70.40	70.40
2	FRONT BUMPER FOG LAMP COVER @$130.20 (N)	NOT NECESSARY	260.40	-
1	FRONT BUMPER TOWING COVER (N)	DEFORMED	29.20	29.20
1	FRONT BUMPER INNER FOAM (N)	CRACKED	219.00	219.00
1	FRONT BUMPER REINFORCEMENT (N)	BENT	495.00	381.60
2	FRONT BUMPER REINFORCEMENT BRACKET @$94.80 (N)	NOT NECESSARY	189.60	-
1	FRONT SUPPORT PANEL (N)	BUCKLED	315.80	315.80
1	FRONT SUPPORT PANEL TOP COVER (N)	NOT NECESSARY	276.70	-
8	FRONT GRILLE CLIP @$6.50 (N)	NECESSARY	52.00	20.00
10	FRONT BUMPER CLIP @$6.50 (N)	NECESSARY	65.00	30.00
1	FRONT BUMPER NUMBER PLATE (N)	NOT NECESSARY	50.00	-
1	FRONT AIR-CON CONDENSER (N)	BENT	655.00	655.00
1	FRONT RADIATOR (N)	DENTED	689.60	689.60
1	FRONT RADIATOR FAN MOTOR ASSY (N)	CRACKED	891.40	891.40
	LESS 10% DISCOUNT		-	-845.35
			9,691.80	7,608.15
	LABOUR			
	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR ,& TOP UP GAS.		280.00	120.00
	TOWING FEE.		150.00	60.00

Report Ref No. CC4/FCI21000178/Ara3q2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING .		100.00	30.00
	PANEL BEATING .		2,000.00	700.00
	SPRAY PAINTING .		1,400.00	600.00
			4,080.00	1,510.00
	GRAND TOTAL		**13,771.80**	**9,118.15**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**7,300.00**

Report Ref No. CC4/FCI21000178/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 1437Y **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 1437Y **RE-INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R