LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CS/TMI21000558/T1QD3E2
Date:	26/01/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000510
Claimant Vehicle No :	SHB3905P	**Insured Vehicle No :**	SMN8304T
Date of Loss:	09/01/2021	Nature of Claim:	TP Claim No: M2100187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHB3905P**		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS061475
Reg. Date:	13/09/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03563344
Colour:	Yellow	Odometer:	548638 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,200.22	1,454.27	745.95	33.90
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,420.00	1,055.00	365.00	25.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**3,631.22**	**2,520.27**	**1,110.95**	**30.59**
Approved Total (Overridden) (S$)		**2,000.00**		
(S$)	3,631.22	2,000.00	1,631.22	44.92
+ GST 7.00/7.00% (S$)	254.19	140.00	114.19	44.92
Nett Amount (S$)	**3,885.41**	**2,140.00**	**1,745.41**	**44.92**

INSPECTION

Date of Assignment:	12/01/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/01/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster:	MOHD TAUFIKH BIN HAMID	**Manager:**	SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2021)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3905P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		***REAR BUMPER**	Torn	458.60 FL	-	*458.60 FL
2	1		***REAR BUMPER CTR GUARD**	Deformed	552.60 FL	-	*552.60 FL
3	1		***REAR BUMPER REINFORCEMENT**	Bent	318.80 FL	-	*318.80 FL
4	10		***REAR BUMPER CLIPS**	Necessary	22.00 FL	-	*22.00 FL
5	1		***REAR BUMPER RETAINER RH**	Not Necessary	112.70 FL	-	*- FL
6	1		***BOOTLID OUTER GARNISH**	Repair	881.90 FL	-	*- FL
7	1		***BOOTLID (HYBRID)**	Necessary	52.40 FL	-	*52.40 FL
8	1		***BOOTLID (PRIUS)**	Necessary	60.80 FL	-	*60.80 FL
9	1		***BOOTLID (ORNAMENT)**	Necessary	52.90 FL	-	*52.90 FL
10	1		***BOOTLID (COMFORTDELGRO)**	Necessary	30.00 FL	-	*30.00 FL
11	1		***BOOTLID (65521111)**	Necessary	30.00 FL	-	*30.00 FL
12	1		***BOOTLID (APPS)**	Necessary	40.00 FL	-	*40.00 FL
13	1		***REAR NO.PLATE WITH TRIM COVER**	Dented	55.00 F	-	*55.00 F
14	1		***REVERSE SENSOR**	Cut	135.70 F	-	*135.70 F
15	1		***REAR BUMPER MAT**	Necessary	50.00 F	-	*50.00 F

F=Franchise part. L=ListItemDisc.

	Repairer's	Reference
Sub Total (S$)	**2,853.40**	**1,858.80**
- List Item Discount on L Items 25.00/25.00% (S$)	653.18	404.53
Total Parts (S$)	**2,200.22**	**1,454.27**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Miscellaneous Items					
1	1	**OD/TP Case (Insurer)**		11.00	11.00
			Sub Total (S$)	**11.00**	**11.00**

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**PANEL BEATING**	New	700.00	525.00
2	**SPRAY PAINTING**	New	600.00	500.00
3	**R/I REVERSE SENSOR**	New	120.00	30.00
	Gross Labour Cost (S$)		**1,420.00**	**1,055.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >