MS CAR AUTO PTE LTD 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875
Tel: 6385-1838 / 9725-4442 Fax: 6386-1838 Email mscarautopl@gmail.com

SJE : ______________________ Vehicle Nos : SLF 5078U
Date of Survey : ______________________ Model : ____________
Contacts : ______________________ Year : ____________

MAKE & MODEL : HONDA STREAM RSZ

ITEM	DESCREPTION	Qty		
1	Rear bumper Dished	1	~~$832.90~~	688
2	Rear bumper br. rackker LH New	1	$38.20	+
3	Rear bumper retainer L+R H New	1	$36.80	/
4	Rear bumper clip New	6	$30.00	/
5	Rear fender ~~L+RH~~ LH Dished	1	$664.60	/
6	Rear fender inner trim L+R H Cracked	1	$352.20	/
7	Rear fender inner trim clip p LH New	6	$30.00	/
8	Tail lamp LH Cracked	1	~~$851.80~~	358
9	Tail lamp panel LH Dented	1	$161.80	/
10	Tail lamp clip L+H New	4	$20.00	+
11	Rear end panel Dented	1	$426.70	/
12	Rear end panel top garnish New	1	$136.70	+
13	Rear end panel bottom garnish New	1	$82.90	+
14	Rear end panel tools garnish New	1	$188.20	+
15	Absorber L-H Bent	1	$385.00	/
16	Knuckle bearing Damaged	1	$268.60	/
17	Lower arm Not new	1	$284.00	+
18	~~Front bonnet~~ Tailgate. Repair	1	~~$938.90~~	203 +
19	~~Bonn et hing~~ Tailgate Hinge New	1	$76.20	+
20	Rear boot w/strip Cut	1	$162.20	/
21	Rear boot w/s g ss mouldig Not new	1	$65.80	+
22	Rear boot emblem -Stream New	1	$52.70	/
23	Rear boot ~~bonnet~~ lock New	1	$56.50	+
24	Rear Knuckle Arm LH. Damaged			
	Parts Sub Total		$6,142.70	
	Discount 20%		$1,228.54	
	Parts Total		$4,914.16	

4013.60
3210.88
397.

	Special Nett			
1	Rear tyre New	1	$156.00	+
2	Rear rim Cut	1	$280.00	/
3	Rear reverse sensor Damaged	1	~~$280.00~~	2w
4	Tail gate glass sealant New	1	$140.00	+
5	Rear end panel sealant New	1	~~$150.00~~	60
	Special Nett Total:		$1,006.00	

540

	Labour			
1	To R & R accident damage parts, to cut/weld, knock and realign accident	1	$1,200.00	1100
	affected area.			
2	To respray accident affected area.	1	$1,200.00	1000
3	To rust proof affected area.	1	$180.00	60
4	To R & R tail gate glass	1	$150.00	120
5	To R & R tail gate mechanism	1	$140.00	80
6	Unde camage system	1	$120.00	✓
9	To R & R reverse sensor, reverse camera and check function 2610	1	$120.00	50
14	To check wheel alignment	1	$100.00	80
	Labour Total		$3,210.00	
	Parts Total		$4,914.16	
	Special Nett Total:		$1,006.00	
	Labour Total		$3,210.00	
	Grand Total		$9,130.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

r/s 20/01/21

080 days

total: 6360.88

L/s: 5K

5K

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44
Premier @ Kaki Bukit
Singapore 415875
Phone Number: 69777077
Fax Number: 69777080

Customer:		Date:	18/1/2021 5:05 PM
Company:	MS	VIN	
License NO:	SLF5078U	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

HONDA, STREAM RN6, RN8 (2WD, 17" Wheel), 06-12 (Customized)

Primary Angles			Initial	Specifications Min.	Specifications Max.	Final
Front	Caster	Left	----	3°20'	5°20'	----
		Right	----	3°20'	5°20'	----
	Camber	Left	-0°12'	-0°45'	0°45'	-0°12'
		Right	0°12'	-0°45'	0°45'	0°12'
	Toe	Left	-0°27'	-0°05'	0°05'	-0°27'
		Right	0°27'	-0°05'	0°05'	0°27'
		Total	0°00'	-0°10'	0°10'	0°00'
Rear	Camber	Left	-1°36'	-1°45'	-0°15'	-1°36'
		Right	-1°24'	-1°45'	-0°15'	-1°24'
	Toe	Left	0°57'	0°03'	0°11'	0°57'
		Right	0°00'	0°03'	0°11'	0°00'
		Total	0°57'	0°05'	0°21'	0°57'
	Thrust Angle		-0°28'	----		-0°28'

Secondary Angles		Initial	Specifications Min.	Specifications Max.	Final
SAI	Left	----	11°05'	11°05'	----
	Right	----	11°05'	11°05'	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----
Toe Curve Change	Left	----	----	----	----
	Right	----	----	----	----
Setback	Front	0.0"	----	----	0.0"
	Rear	-0.3"	----	----	-0.3"
Track Width Diff.		0.3"			0.3"
Wheel Base Diff.		0.3"			0.3"
Front Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Rear Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Frame Angle					----

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44
Premier @ Kaki Bukit
Singapore 415875
Phone Number: 69777077
Fax Number: 69777080

Customer:		Date:	28/1/2021 10:00 AM
Company:	MS	VIN	
License NO:	SLF5078U	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

HONDA, STREAM RN6, RN8 (2WD, 17" Wheel), 06-12 (Customized)

Primary Angles			Initial	Specifications Min	Specifications Max	Final
Front	Caster	Left	----	3°20'	5°20'	----
		Right	----	3°20'	5°20'	----
	Camber	Left	-0°06'	-0°45'	0°45'	-0°06'
		Right	0°06'	-0°45'	0°45'	0°06'
	Toe	Left	0°03'	-0°05'	0°05'	0°00'
		Right	-0°03'	-0°05'	0°05'	0°00'
		Total	0°00'	-0°10'	0°10'	0°00'
Rear	Camber	Left	-1°24'	-1°45'	-0°15'	-1°24'
		Right	-1°18'	-1°45'	-0°15'	-1°18'
	Toe	Left	0°03'	0°03'	0°11'	0°03'
		Right	-0°06'	0°03'	0°11'	0°03'
		Total	-0°03'	0°05'	0°21'	0°06'
	Thrust Angle		-0°04'	----		0°00'

Secondary Angles		Initial	Specifications Min	Specifications Max	Final
SAI	Left	----	11°05'	11°05'	----
	Right	----	11°05'	11°05'	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----