LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001198/EVD3E2
Date: 24/02/2021

REFERENCE

Insured/Claimant:	ANGELINE SOO CHYIN LING	Policy No:	1900258914		
Date of Loss:	25/01/2021	Nature of Claim:	OD	Claim No:	1168846198SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SGF7549Z**		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH738881
Reg. Date:	03/01/2020 (Man. Year: 2019)	Chassis No:	KNAF5416ML5059880
Colour:	Grey	Odometer:	20909 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S$85,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,843.22	5,489.60	3,353.62	37.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,020.00	4,110.00	2,910.00	41.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**15,863.22**	**9,599.60**	**6,263.62**	**39.49**
- Excess (S$)	300.00	300.00	0.00	0.00
(S$)	15,563.22	9,299.60	6,263.62	40.25
+ GST 7.00/7.00% (S$)	1,089.43	650.97	438.46	40.25
Nett Amount (S$)	**16,652.65**	**9,950.57**	**6,702.08**	**40.25**

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE **Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***SUNDRIES**	Necessary	20.00 FS	*20.00 FS
2	1		***LAMP ASSY-HEAD, LH**	Broken	2,210.00 FL	*2,210.00 FL
3	1		***PANEL ASSY-HOOD**	Dented	1,502.00 FL	*1,502.00 FL
4	1		***HINGE ASSY-HOOD, LH**	Not Necessary	43.00 FL	*- FL
5	1		***HINGE ASSY-HOOD, RH**	Not Necessary	43.00 FL	*- FL
6	1		***CLIP-HOOD INSULATING PAD MTG** (9 pcs)	Necessary	13.00 FL	*9.00 FL
7	1		***LATCH ASSY-HOOD**	Not Necessary	103.00 FL	*- FL
8	1		***PANEL-FENDER, LH**	Dented	430.00 FL	*430.00 FL
9	1		***GUARD ASSY-FRONT WHEEL, LH**	Crushed	95.00 FL	*95.00 FL
10	1		***CARRIER ASSY-FRONT END MODULE**	Not Necessary	675.00 FL	*- FL
11	1		***BEAM COMPLETE-FR BUMPER**	Not Necessary	497.00 FL	*- FL
12	1		***COVER-FR BUMPER**	Dented	633.00 FL	*633.00 FL
13	1		***GRILLE-FRONT BUMPER**	Cut	485.00 FL	*485.00 FL
14	1		***LAMP ASSY-FRONT FOG, LH**	Not Necessary	303.00 FL	*- FL
15	1		***MOULDING-FRONT BUMPER, LH**	Not Necessary	216.00 FL	*- FL
16	1		***LAMP ASSY-SIDE REPEATER, LH**	Not Necessary	143.00 FL	*- FL
17	1		***AIR DUCT-FR BUMPER, LH**	Not Necessary	14.00 FL	*- FL
18	1		***ABSORBER-FRONT BUMPER ENERGY**	Not Necessary	84.00 FL	*- FL
19	1		***STIFFNER-FR BPR LWR**	Not Necessary	114.00 FL	*- FL
20	1		***BRACKET-FR BUMPER UPR SIDE MTG**	Broken	22.00 FL	*22.00 FL
21	1		***WIRING ASSY-BUMPER EXTENSION**	Not Necessary	207.00 FL	*- FL
22	2		***ULTRASONIC SENSOR ASSY-P.A.S**	Not Necessary	326.00 FL	*- FL
23	1		***ORNAMENT-KIA NO.115**	Necessary	32.00 FL	*32.00 FL
24	1		***GARNISH-RADIATOR GRILLE**	Not Necessary	38.00 FL	*- FL
25	1		***GRILLE ASSY-RADIATOR**	Not Necessary	328.00 FL	*- FL
26	1		***MOULDING ASSY-SIDE SILL, LH**	Not Necessary	279.00 FL	*- FL
27	1		***PANEL ASSY-FRONT DOOR, LH**	Dented	1,277.00 FL	*1,277.00 FL
28	1		***HINGE ASSY-FRT DOOR UPP, LH**	Bent	30.00 FL	*30.00 FL
29	1		***HINGE ASSY-FRT DOOR LWR, LH**	Bent	27.00 FL	*27.00 FL
30	1		***BLACK TAPE-FR DR RR, LH**	Necessary	13.00 FL	*13.00 FL
31	1		***LATCH ASSY-FRONT DOOR, LH**	Not Necessary	400.00 FL	*- FL
32	1		***MOULDING ASSY-FRT DR FRAME, LH**	Necessary	72.00 FL	*72.00 FL
33	1		***W/STRIP ASSY- FR DR BELT O/S RH**	Not Necessary	80.00 FL	*- FL
34	1		***W/STRIP ASSY-FR DR SIDE LH**	Not Necessary	102.00 FL	*- FL
35	1		***W/STRIP-FR DR BODY SIDE LH**	Not Necessary	125.00 FL	*- FL
36	1		***W/STRIP-FR DR BELT I/S LH**	Not Necessary	43.00 FL	*- FL
37	1		***COOLANT (4L)**	Not Necessary	26.00 FN	*- FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S$)	**11,050.00**	**6,857.00**
- List Item Discount on L Items 20.00/20.00% (S$)	2,200.80	1,367.40
- Nett Item Discount on N Items 23.00/23.00% (S$)	5.98	0.00
Total Parts (S$)	**8,843.22**	**5,489.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	**RENEW BONNET, FRT BUMPER, LHF FENDER & LHF DOOR. REPAIR LHF DOOR PILLAR, LH CENTRE PILLAR, LHF WHEELHOUSE & LHR DOOR**	New	2,800.00	1,600.00
2	**RESPRAY FRT BUMPER, LHF FENDER, LHF WHEELHOUSE PNL, BONNET, LHF DOOR PILLAR, LHF DOOR, LHR DOOR & LH SIDE SILL GARNISH**	New	3,150.00	1,750.00
3	**REMOVE & REFIT AC COND & RADIATOR**	New	100.00	0.00
4	**TOP UP AIRCON GAS**	New	80.00	0.00
5	**REMOVE & REFIT LHF DOOR COMPONENT**	New	120.00	120.00
6	**CHECK WIRING ELECTRICAL SYSTEM**	New	30.00	30.00
7	**TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST**	New	120.00	120.00
8	**SUPPLT FRT NUMBER PLATE WITH CASING**	New	50.00	0.00
9	**REMOVE & REFIT FRT PARKING ASSIST SENSOR**	New	60.00	60.00
10	**APPLY ANTI CORROSION ON AFFECTED AREAS**	New	80.00	-
11	**SUPPLY BODY PNL SEALANT**	New	80.00	80.00
12	**RESPRAY LH REAR DOOR** (Supplementary)	New	350.00	350.00
	Gross Labour Cost (S$)		**7,020.00**	**4,110.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >