AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GUI KIAN HOE
308C PUNGGOL WALK
#08-348
SINGAPORE 823308

ATTN:

LKK
130

Estimate No:	**MC1901832**
Date:	19 Mar 2021
Policy No:	PNPV2020-00006373
Veh Reg No:	**SDD131L**
Make/Model:	NISSAN X-TRAIL 2.0 CVT

Your Ref No:	SDD131L
Claim Type:	Third Party
Accident Date:	18/03/2021
TP Veh Reg No:	SLB1369C

Not Withside
Reserve B&paint
4. Jan

Estimate Repair Cost to Vehicle No :SDD131L

	Description	Quantity	List Price S$	Amount S$
	SPARE PARTS			
1	TAILGATE	1 PC	4,380.00	
2	TAILGATE TRIM	1 PC	474.10	
3	TAILGATE EMBLEM	1 PC	76.10	
4	TAILGATE XTRAIL LOGO	1 PC	110.00	
5	TAILGATE INNER LOCK	1 PC	613.70	
6	REAR BUMPER	1 PC	693.10	
7	REAR BUMPER SIDE RETAINER LH & RH	2 PC	92.20	
8	REAR BUMPER CLIPS	15 PC	76.50	
9	REAR BUMPER CHROME MOULDING	1 PC	171.00	
10	REAR BUMPER CTR CVR	1 PC	129.30	
11	REAR BUMPER SILVER COVER - CHECK PRICE	1 PC	0.00	56.50
12	REAR BUMPER REINFORCEMENT	1 PC	569.20	
13	REAR BUMPER REINFORCEMENT BRACKET LH & RH	2 PC	391.20	
14	REAR FENDER WHEEL ARCH LH & RH	2 PC	370.60	
15	REAR WINDSCREEN MOULDING LWR	1 PC	84.10	
16	REAR END PANEL	1 PC	499.30	
17	REAR BUMPER TOP BRACKET	1 PC	782.50	
			9,512.90	
		Less 10%	951.29	8,561.61
18	REAR EXHAUST PIPE	1 PC	1,244.30	
19	REAR EXHAUST PIPE MOUNTING	2 PC	29.80	
20	REVERSE SENSOR CTR	SHORTED / ~~2~~ PC	488.00	
			1,762.10	
		Less 5%	88.11	1,674.00
	Special Nett			
21	INNER SEAL	1 PC	20.00	
22	WINDSCREEN SEALANT	1 PC	40.00	
			60.00	60.00
	LABOUR			
23	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
24	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
25	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
26	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	

AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GUI KIAN HOE
308C PUNGGOL WALK
#08-348
SINGAPORE 823308

ATTN:

Estimate No: **MC1901832**
Date: 19 Mar 2021
Policy No: PNPV2020-00006373
Veh Reg No: **SDD131L**
Make/Model: NISSAN X-TRAIL 2.0 CVT

Your Ref No: SDD131L
Claim Type: Third Party
Accident Date: 18/03/2021
TP Veh Reg No: SLB1369C

Estimate Repair Cost to Vehicle No :SDD131L

	Description	Quantity	List Price	Amount
			S$	S$
27	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL,FRONT FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	500-
28	TO SPRAY TAILGATE,TAILGATE TRIM,REAR BUMPER, END PANEL,SPARE TYRE PANEL,FRONT FENDER LH.	1 PC	1,000.00	800
			2,200.00	2,200.00
			Total	S$ 12,495.61
			Add GST @ 7%	874.69
			Total Amount Payable	S$ 13,370.30

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND THREE HUNDRED SEVENTY AND CENTS THIRTY ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

*SUPP PARTS

REAR END PANEL INNER	230.20	(BENT)
REAR BOOR RUBBER - 50%	74.40	(CUT)

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: