ASS. REC. BY: Steve | REF: CC4/LPC 21003769/pa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGC 9339R Yr Regn: 23/12/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz E200 c.c 1991

Colour Gy A/C: Insured / Std / NI / N

Sp.Reading 63459 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: WDB2120342B095192

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl : NII / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or GENERAL

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	14/3/21	D.O.I.	6/4/21

Survey held at Cycle & carriage, Mercedes

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-100K

Date/Time, File Pass to?

Date/Time, File Return to?

☐ : Prell. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

S + RS S

Photos

Others

TOTAL

Mercedes-Benz

Steve (LKK) 6/4/21, 10.30am
W/ PL
P/P
My BAL Sly
4 days

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC9339R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No	48961
Reg No/Reg Date	SGC9339R / 23/12/2014
Date In/Mileage	
Chassis No	WDD2120342B095192
Engine No	27492030307485
Make/Model	MB/E 200 2.0 CGI SEDAN (W212
Colour/Trim	027 755 Tenorite Gr/ 042 258 Basalt Grey

SGC9339R

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	15/03/2021/ 18:19	CH	371 / Go Chee Han

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : GA148647/1 // 14-3-2021				
DRIVE IN/TP VEH NUMBER : 15-3-2021 // GBD5811Z - LONPAC				
DATE IN/DATE SURVEY:				
DIRECT SETTLEMENT BY:				
A BPILAB				960 1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				1200 1500.00
A BPIRES				
RESPRAY REAR BUMPER & TRUNK LID			0.10	380.00
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB				
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M REAR BUMPER 00	1.00	1668.90	00.00	1668.90
M REAR BOTTOM BLACK TRIM BUMPER CUT	1.00	247.17	00.00	247.17
M REAR BUMPER CHROME MOULDING CUT	1.00	169.95	00.00	169.95
M LH/REAR BUMPER CHROME MOULDING NPC	1.00	137.18	00.00	137.18
M RH/REAR BUMPER CHROME MOULDING NPC	1.00	137.18	00.00	137.18
M LEFT BOTTOM BRACKET ?	1.00	24.88	00.00	24.88
M RIGHT BOTTOM BRACKET ?	1.00	24.88	00.00	24.88
M CTR/BASIC MOUNTING FOR BUMPER ?	1.00	267.18	00.00	267.18
M GROMMET NPC	3.00	2.64	00.00	7.92
M MERCEDES STAR NPC	1.00	49.73	00.00	49.73
M E200 MODEL PLATE NPC	1.00	91.89	00.00	91.89
M OUTER RIGHT REAR LAMP COMBINATION X	1.00	704.32	00.00	704.32

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Nett		7,451.18
7% GST on	7451.18	521.58
Total Payable		7,972.76

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg