KB

ESTIMATE

RC AUTO

Not Authorised
Liability 8 4250/-
Recovery After Repair

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel: 97619383 Email: rcauto5555@gmail.com
Reg. No. 53194138K

SKD 6118 D

Date : 07.03.2021

Quantity	Description/Particulars	Unit Price	Amount		
1 PC	REAR BUMPER	R	2700	00	X
1 PC	REAR SPORTS RIM 2300	Bd	3200	00	✓
1 PC	REAR KNUCKLE ARM	Bn	1860	00	✓
1 PC	REAR TOP ARM	Sn	1900	00	X
1 PC	REAR LOWER ARM	Dn	480	00	✓
1 PC	REAR TRUST ARM	Dn	390	00	✓
	TOTAL (LESS 10%)		9477	00	
	10%				
	WHEEL ALIGNMENT		80	00	✓
	TO RESPRAY REAR BUMPER AND FENDER		500	00	480d
	LABOUR CHARGES FOR UNDERCARRIAGE REPAIR		450	00	250d
	TYRE	Sn	350	00	X
		TOTAL	10857	00	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Received the above goods in good order and condition

For RC AUTO

Received by

B.S.D.E.

Authorised Signature