SMK408X.

TP Budget Direct.
Veron.

Toyota Vios 1496cc

MR2B23F3X01171301

Rear Bumper Deformed 440.10. ✓

Rear Bumper Clips. New 30(SN) ✓

Rear Bumper Side Holder x02 New 66.1x2 = 123.20. ✓

Rear Bumper Reflector LH. Cracked 120.40 ✓

Rear Bumper Reinforcement. Dented 343.80 ✓

Rear Bumper Reinforcement Bracket x02. New 114.8x2 = 229.60 X

Reverse Sensor ~~x02~~ Dmgd ~~280(SN)~~ 200(SN)

Rear End Panel. Dented 768 ✓

Rear End Panel Top Garnish. New New 205.60 X

Rear End Panel Top Garnish Clips. New New 20(SN) X

Rear End Panel Sealant. New 60(SN) ✓

Taillamp LH. Cracked 422.50. ✓

SMK 408X.

Toyota Logo.	Not Nee	50.20 ✗
Vios Emblem.		43.60 ✗
E Emblem.		45.50 ✗
Panel Beating.		~~800~~ 600
Spray Painting.		~~800~~ 500
Wiring.		~~50~~ 30
To remove reverse sensor		~~100~~ 50
To remove upholstery.		~~150~~ 50
To spray tuff coat		~~150~~ 60

5232.90

List: 2218 Labour: 1290

Less 25%: 1663.50. Total: 3243.50

S.N: 290 L/S: 26K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: