# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

CHINA TAIPING INSURANCE (S) PTE LTD	**Ref:** CS3/TPS21005653/Uvf3e2
C/O: TOPLIS AND HARDING (S) PTE LTD 133 CECIL STREET #17-01A KECK SENG TOWER SINGAPORE 069535	**Date:** 27/05/2021
	Code: CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PUBLIC LIABILITY	**Veh. Inspected**	GBA 9Y
Policy No.	W211305	**Coverage ($)**	0.00
Claim No.	SNE21D200033	**Excess ($)**	0.00
Assign From	SHARON	**Assign Date**	10/05/2021

2. Vehicle Particulars & Condition

Make & Model	RENAULT KANGOO (A)	**c.c**	1461
Engine No.	HIDDEN	**Year of Reg.**	2006
Chassis No.	VF1FC1EAF36539026	**Colour**	SILVER
Odometer	149799 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	NIL
General	GOOD		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	175/65 R14	HANKOOK	6 mm
L/H Front Tyre	175/65 R14	HANKOOK	6 mm
R/H Rear Tyre	175/65 R14	HANKOOK	6 mm
L/H Rear Tyre	175/65 R14	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND FRONT WINSCREEN BROKEN.

5. General Information

Accident Date	25/04/2021	**Inspect Date / Time**	10/05/2021 (01:26 PM)
Survey held at	ESPACE SERVICE CENTRE BLK 3021A #01-41 UBI RD 1 SINGAPORE 408715		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000-$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

Report Ref No. CS3/TPS21005653/Uvf3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser