LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21007876/KES3Q2
Date: 05/11/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447		
Claimant Vehicle No :	SLV6473X	**Insured Vehicle No :**	SLM7658X		
Date of Loss:	21/07/2021	Nature of Claim:	TP	Claim No:	MFL2021D0003071

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SLV6473X**		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4406242
Reg. Date:	09/01/2018 (Man. Year: 2016)	Chassis No:	RU11206242
Colour:	Metallic Black	Odometer:	72257 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,370.56	2,129.68	240.88	10.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,270.00	470.00	27.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**4,110.56**	**3,399.68**	**710.88**	**17.29**
+ GST 7.00/7.00% (S$)	287.74	237.98	49.76	17.29

Nett Amount (S$)	**4,398.30**	**3,637.66**	**760.64**	**17.29**

+ Car Rental (7.0 x S$100.00/day) (S$)	700.00
+ Doc/Search Fee (S$)	7.49
Nett Liability (S$)	**4,345.15**
Global Sum Settlement (S$)	**4,300.00**

INSPECTION

Date of Assignment: 23/07/2021

Date Inspected: 26/07/2021

Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV6473X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***REAR TAILGATE**	Bent	1,037.00 FL	*953.00 FL
2	1		***REAR BUMPER**	Bent	553.10 FL	*508.80 FL
3	1		***REAR BUMPER SIDE RH**	Serviceable	172.80 FL	*- FL
4	4		***REAR BUMPER CLIPS**	Necessary	14.00 FL	*14.00 FL
5	1		***REAR VEZEL EMBLEM**	Necessary	38.80 FL	*38.80 FL
6	2		***REAR WINDSCREEN MOULDING**	Necessary	62.00 FL	*62.00 FL
7	1		***REAR END PANEL**	Bent	452.40 FL	*452.40 FL
8	1		***REAR END PANEL TOP COVER**	Dented	55.80 FL	*55.80 FL
9	1		***SET REAR PARKING SENSOR WITH INSTALLATION**	Shorted	200.00 FS	*200.00 FS
10	1		***SEALANT**	Necessary	40.00 FS	*40.00 FS
11	1		***REAR FENDER ARCH GARNISH RH**	Necessary	172.10 FL	*172.10 FL
12	1		***REAR TAILGATE WEATHERSTRIP**	Necessary	105.20 FL	*105.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**2,903.20**	**2,602.10**
- List Item Discount on L Items 20.00/20.00% (S$)	532.64	472.42
Total Parts (S$)	**2,370.56**	**2,129.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**TO TRANSFER REAR CAMERA**	New	40.00	40.00
2	**TO REMOVE +REFIX REAR WINDSCREEN**	New	140.00	120.00
3	**TO STRAIGHTEN REAR BODY ,TO KNOCK DENTS ON REAR TYRE PANEL AND RENEW OF PARTS**	New	800.00	600.00
4	**TO SPRAY PAINT**	New	700.00	450.00
5	**TO DISMANTLE +REFIT REAR FENDER SIDE TRIM LH ,PASSENGER SEAT ,ETC**	New	60.00	60.00
		Gross Labour Cost (S$)	**1,740.00**	**1,270.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >