# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO21007901/Ktf3e2
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Date:	29/07/2021
		Code:	SMO

1.	Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh.	SFR 1066M	**Veh. Inspected**	PC 6693E
Policy No.		**Coverage ($)**	0.00
Claim No.	CMTD2102176/GPL	**Excess ($)**	0.00
Assign From	MELVIN YE	**Assign Date**	26/07/2021

2.	Vehicle Particulars & Condition		
Make & Model	TOYOTA HIACE GL	**c.c**	2982
Engine No.	HIDDEN	**Year of Reg.**	2017
Chassis No.	KDH2230031749	**Colour**	SILVER
Odometer	113817 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	NIL
General	GOOD		

3.	Conditions of Tyres		
	Size	**Make**	**Balance**
R/H Front Tyre	195 R15X8	DUNLOP	7 mm
L/H Front Tyre	195 R15X8	DUNLOP	7 mm
R/H Rear Tyre	195 R15X8	DUNLOP	7 mm
L/H Rear Tyre	195 R15X8	DUNLOP	7 mm

4.	Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	

5.	General Information		
Accident Date	21/07/2021	**Inspect Date / Time**	26/07/2021 (10:28 AM)
Survey held at	TEAM AUTOPRO PTE LTD		
	160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

Report Ref No. CS3/SMO21007901/Ktf3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser