LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CC4/AIG21008063/TGA3Q2
Date:	18/04/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100500484-04
Claimant Vehicle No :	SHC7300C	**Insured Vehicle No :**	SLL3308M
Date of Loss:	28/07/2021	Nature of Claim:	TP	Claim No: 6817775749SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHC7300C**		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS055646
Reg. Date:	12/07/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU403561105
Colour:	Yellow	Odometer:	399004 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,141.55	1,902.45	239.10	11.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,305.00	425.00	24.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**3,871.55**	**3,207.45**	**664.10**	**17.15**
Approved Total (Overridden) (S$)		**2,400.00**		
(S$)	3,871.55	2,400.00	1,471.55	38.01
+ GST 7.00/7.00% (S$)	271.01	168.00	103.01	38.01
Nett Amount (S$)	**4,142.56**	**2,568.00**	**1,574.56**	**38.01**
+ Loss of Use (5.0 x S$50.00/day) (S$)		250.00		
+ Car Rental (5.0 x S$125.40/day) (S$)		627.00		
+ Doc/Search Fee (S$)		2.00		
Nett Liability (S$)		**3,447.00**		
Global Sum Settlement (S$)		**3,400.00**		

INSPECTION

Date of Assignment:	29/07/2021	
Date Inspected:	30/07/2021 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID		**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	458.60 FL	*458.60 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER UNDER COVER	Deformed	552.60 FL	*552.60 FL
4	1		*REAR BUMPER BEAM	Not Necessary	318.80 FL	*- FL
5	1		*BOOTLID LOWER GARNISH	Cracked	889.70 FL	*889.70 FL
6	1		*BOOTLID EMBLEM -PRIUS	Necessary	60.80 FL	*60.80 FL
7	1		*BOOTLID EMBLEM -HYBRID	Necessary	52.40 FL	*52.40 FL
8	1		*BOOTLID EMBLEM -TOYOTA STAR	Necessary	52.90 FL	*52.90 FL
9	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
10	1		*BOOTLID COMFORTDELGRO LOGO	Necessary	30.00 FS	*30.00 FS
11	1		*BOOTLID TEL NOS LOGO	Necessary	30.00 FS	*30.00 FS
12	1		*BOOTLID APPS LOGO	Necessary	40.00 FS	*40.00 FS
13	1		*REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
14	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**2,743.50**	**2,424.70**
- List Item Discount on L Items 25.00/25.00% (S$)	601.95	522.25
Total Parts (S$)	**2,141.55**	**1,902.45**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**PANEL BEATING**	New	800.00	525.00
2	**SPRAY PAINT**	New	600.00	500.00
3	**REMOVE/REFIX REVERSE SENSOR**	New	80.00	30.00
4	**ADVERTISEMENT LOGO-BUMPER**	New	50.00	50.00
5	**ADVERTISEMENT LOGO-FENDER**	New	200.00	200.00
		Gross Labour Cost (S$)	**1,730.00**	**1,305.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >