Re: E/3455/2021 - SBS8418C with WB3313U

Ang Chong Boon <angcb@sbstransit.com.sg>
Thu 8/12/2021 11:13 AM

Estimate for

Stock Code	Description	Quantity	Total Material cost(S$)
		0	$0.00
30541659	SIDE SIGNAL LIGHT ASSY	1	$16.00
30103953	NOSING RUBBER EDGE;ENT DR	1	$184.00
30117419	GLASS.SIDE.NO 1.1660X1228MM. A & B .N/S	1	$204.00
30122008	RUBBER;GLIDE DR;BLACK Q-445	1	$56.00
	(MO Number : BN2108000790)	Sub Total S$:	460.00

- [ ] Parts cost: $ 460
- [ ] Contractor Labour cost: $ 750 ✓ +gst
- [ ] Workshop Labour cost: $ 184 Xnn
- [ ] Advertisement Cost: $ 0 Xnn
- [ ] Repair period: 3 days

- [ ] Tow Cost: $ 0 Xnn.
- [ ] Loss of use: $ Lkk don't require Xnn
- [ ] Overheads: $ 418.20 Xnn

2days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: