LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:	CS/AIG21008637/UQF3N2
Date:	29/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900230217
Claimant Vehicle No :	GBH5037X	**Insured Vehicle No :**	SMQ2093A
Date of Loss:	14/08/2021	Nature of Claim:	TP Claim No: 0520856049SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**GBH5037X**		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Engine No:	YD25424359A
Reg. Date:	25/06/2018 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008833
Colour:	Silver	Odometer:	148486 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,047.84	1,067.04	7,980.80	88.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,080.00	1,870.00	63.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**11,997.84**	**2,147.04**	**9,850.80**	**82.10**
Approved Total (Overridden) (S$)		**1,700.00**		
Nett Amount (S$)	**11,997.84**	**1,700.00**	**10,297.84**	**85.83**

INSPECTION

Date of Assignment:	17/08/2021
Date Inspected:	24/08/2021 Inspected At:
Estimated Period of Repair:	3.0 days

Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
Singapore 417883

Adjuster:	MARCUS CHUA	**Manager:**	SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	750.00 FN	*571.90 FN
2	1		*FRONT BUMPER REFORMENT	Not Necessary	550.00 FN	*- FN
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	55.00 FN	*- FN
4	1		*FRONT CORNER GARNISH L/H	Not Necessary	220.00 FN	*- FN
5	1		*FRONT BUMPER RETAINER L/H	Not Necessary	185.00 FN	*- FN
6	1		*FRONT BUMPER LIP	No such part	500.00 FN	*- FN
7	1		*FRONT HEADLIGHT GARNISH L/H	No such part	255.00 FN	*- FN
8	1		*FRONT HEADLAMP L/H	Cracked	2,550.50 FN	*441.40 FN
9	1		*FRONT STEP PANEL L/H	Repair	350.00 FN	*- FN
10	1		*FRONT STEP PANEL GARNISH L/H	Grazed	150.00 FN	*122.30 FN
11	1		*FRONT DOOR MIRROR L/H	Not Necessary	1,500.00 FN	*- FN
12	1		*FRONT DOOR HINGE L/H	Not Necessary	150.00 FN	*- FN
13	1		*FRONT MAIN MIRROR L/H	Not Necessary	900.00 FN	*- FN
14	1		*FRONT DOOR L/H	Repair	1,580.50 FN	*- FN
15	2		*FRONT DOOR HINGE	Not Necessary	301.60 FN	*- FN
16	1		*SET FRONT BUMPER CLIPS	Necessary	15.00 FS	*15.00 FS
17	1		*FRONT HEAD LAMP CLIPS	Not Necessary	5.00 FS	*- FS
18	1		*COMPANY STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S$)	**10,047.60**	**1,180.60**
- Nett Item Discount on N Items 10.00/10.00% (S$)	999.76	113.56
Total Parts (S$)	**9,047.84**	**1,067.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	**TO RESPRAY PAINTING AND COMPANY STICKER**	New	1,200.00	680.00
2	**TO RESPRAY UNDERCOATING ON ACCIDENT PART**	New	250.00	0.00
3	**PANEL BEATING,CUT,WELD,REMOVE & REPLACE ABOVE PARTS**	New	1,500.00	400.00
	Gross Labour Cost (S$)		**2,950.00**	**1,080.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >