LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805   Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16 Singapore 079120	**Our File No:** CC3/AIG21009265/ATCN2 **Date:** 09/09/2021

REFERENCE

Insured/Claimant:	ARUN ROSHAN GANESH	Policy No:	7210102679		
Date of Loss:	31/08/2021	Nature of Claim:	OD	Claim No:	6231309671SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SNB4893L**		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM032671
Reg. Date:	25/08/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF58MA052686
Colour:	White	Odometer:	265 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S$195,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,725.00	5,796.00	1,929.00	24.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,772.00	3,402.00	3,370.00	49.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**14,497.00**	**9,198.00**	**5,299.00**	**36.55**
+ GST 7.00/7.00% (S$)	1,014.79	643.86	370.93	36.55
Nett Amount (S$)	**15,511.79**	**9,841.86**	**5,669.93**	**36.55**

INSPECTION

Date of Assignment:	02/09/2021		
			Premium Automobiles Pte Ltd (UBI)
Date Inspected:	02/09/2021	Inspected At:	55 Ubi Road 1
			Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING   **Manager:**   DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S$675.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***REAR DOOR-RH**	Dented	3,884.00 FS	*3,884.00 FS
2	1		***REAR DOOR SEAL-RH**	Necessary	222.00 FS	*222.00 FS
3	1		***BONDING AGENT**	*Check	49.00 FS	*- FS
4	1		***CLEANING SOLUTION**	*Check	68.00 FS	*- FS
5	1		***APPLICATOR**	*Check	8.00 FS	*- FS
6	1		***REAR DOOR ATTACHMENT PART**	Not Necessary	173.00 FS	*- FS
7	1		***REAR DOOR CATCH-RH**	*Check	120.00 FS	*- FS
8	1		***REAR DOOR SIDE MEMBER TRIM-RH**	Repair	869.00 FS	*- FS
9	1		***REAR DOOR SIDE MEMBER ATTACHMENT PARTS**	*Check	130.00 FS	*- FS
10	1		***ADHESIVE TAPES**	Not Necessary	212.00 FS	*- FS
11	1		***REAR ALUMINIUM RIM-RH**	Cut	1,690.00 FS	*1,690.00 FS
12	1		***SUNDRIES**	*Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

	Total Parts (S$)	7,725.00	5,796.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	**TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES**	New	400.00	280.00
2	**TO REMOVE AND RENEW RHS REAR DOOR AND RHS SILL PANEL TRIM.TO REPAIR RHS REAR FENDER,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED**	New	2,800.00	1,000.00
3	**TO RESPRAY RHS REAR DOOR,RHS REAR DOOR HANDLE,RHS REAR FENDER AND RHS SILL PANEL TRIM**	New	3,100.00	1,650.00
4	**TO RENNEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT**	New	280.00	280.00
5	**TO CARRY OUT DIAGNOSTIC CHECK**	New	192.00	192.00
	Gross Labour Cost (S$)		**6,772.00**	**3,402.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >