LKK Auto Consultants Pte Ltd
Company Registration No. 199607198R
51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DM18HO03349/SG

Date: 15th Dec 2021

Our Ref: CS1/LAW21009656/Uvf3e2

M/s EQ Insurance Company Ltd
C/o: Willy Tay's Chambers
70 Shenton Way
#17-02 Eon Shenton
Singapore 069110

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YM 6079U
INSURED VEHICLE: YP 8938L
ACCIDENT DATE: 03/12/2018

We thank you for your instruction on 14/09/2021.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of YM 6079U from M/s Carlink Consultancy.
b) Final Repair Bill of YM 6079U from M/s TwinCar Automotive Pte Ltd.
c) Survey report by JP Knights Pte Ltd with colour photographs.
d) Singapore Accident Statement of Vehicles YM 6079U and YP 8938L.
e) Police Report of Vehicles YM 6079U
f) Colour damaged vehicle photographs of YM 6079U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YP 6079U
Make & Model	: Isuzu NHR85EU3ES
Chassis Number	: JAANHR85E77100047
Year of Registration	: 2007
Engine Capacity	: 2999 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.