COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC 503E

MAKE HYUNDAI

MODEL IONIQ

DATE: 27/10/2021

MVA JUMANI

DOA: 27. Oct. 2021

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY			$459.40	Cut
1	REAR BUMPER CENTRE MLDG			$451.25	Cut
1	REAR BUMPER BEAM			$394.80	rsvc
1	REAR BUMPER REFLECTOR RH			$41.45	Cvg
10	REAR BUMPER CLIPS			$22.00	nec
1	REAR BUMPER BEAM BRACKET RH			$138.10	rsvc
1	REAR BUMPER SIDE COVER RH			$108.00	Cut
1	REAR BUMPER SIDE BRACKET RH			$55.80	nec
1	REAR FENDERRLH			$1,768.30	Rep
1	TAILLAMP ASSY RH			$870.40	scr
1	REFLECTOR RH			$41.45	replcat
				$4,350.95	
	SUB TOTAL			**$4,350.95**	
	LESS 20%			$870.19	
	DISCOUNTED TOTAL			**$3,480.76**	
	REVERSE SENSOR			$180.00	NET Cut
	ADVERTISEMENT LOGO – FENDER			$200.00	NET nec
				$380.00	
	Labour Charge				
	PANEL BEATING			$1,200.00	700
	SPRAY PAINT			$600.00	500
	REMOVE/REFIX REVERSE SENSOR			$500.00	20
	CHECK WIRING			$50.00	20
	TUFF KOTE			$50.00	20
	REMOVE/ REFIX REAR UPHOLSERY REAR			$120.00	100
	TOTAL LABOUR			**$2,520.00**	
	ESTIMATE TOTAL			**$6,365.20**	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thevan@Lkhauto.com
82235769
27/10/21 16/5
3clays wp
L/S after repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.