(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/MSG2101335/Urf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR7040A

at Workshop m/s ZOOM

of

Insured: SMK7125

Policy No. A29142301AT2

Claims No. 638717

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $ 19k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 680D

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJR7040A Yr Regn: 09/07/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA

Make: Honda Jazz c.c 1339

Colour yellow A/C: Insured / Std / NI / NA

Sp.Reading 154646 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGE68509S209534

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50 R16 KUMHO Aplus

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	5/11/21	D.O.I.	8/11/21

Survey held at —

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear & frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	cee until 05-07-2024 DTA $8136
	3rd 2yrs. fnbk NETT $1086.4
	have scene photo on front portion
	frt portion No said on police report?
16/11/21	L/S $ 4500 confirmed with Elin (Red 8780.80, 66%)

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2) 16/11/21-typist

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL

Report Format : Merimen

Lump Sum / ~~I.B.I.~~ ($ 4500)

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorised
Dele
8/11/21
2/S$4500/
7 days.

11 November 2021

REG NO. : SJR 7040 A
MAKE/MODEL : HONDA JAZZ

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION				AMT(S$)
	LIST ITEMS				
1	Rear windscreen moulding	Nel		$	62.90
1	Rear tailgate	DD		$	762.20
2	Rear tailgate dampers	" "		$	219.00
1	Rear tailgate inner lock	Jm/Tw1		$	168.50
1	Rear tailgate inner trim board	Re/CN		$	194.40
1	Rear tailgate logo	" "		$	22.50
1	Rear tailgate outer garnish	" "		$	112.30
1	Rear tailgate rubber	SVC		$	89.80
1	Rear tailgate "JAZZ" emblem	Nel		$	28.80
2	Rear taillamps	N/Scne OLSnn	284.20	$	674.00 LPC
1	Rear end panel	"		$	296.60
1	Rear end panel inner garnish	" "		$	58.40
1	Rear bumper	Re/To.n	466.20	$	520.80
2	Rear bumper side retainers	Nel		$	37.20
1	Rear spare tyre board	" "		$	179.70
1	Rear spare tyre panel	R		$	737.00
1	Rear exhaust silencer	" "		$	462.40
2	Rear exhaust mountings	" "		$	57.00
1	Front bonnet	" "		$	516.90
1	Front bonnet lock	" "		$	115.30
2	Front headlamps	" "		$	1,171.20
1	Front grille	" "		$	137.50
1	Front grille logo	" "		$	34.70
1	Front bumper	R		$	560.90
2	Front bumper fog lamps	" "		$	570.00
1	Front bumper reinforcement	R		$	282.20
2	Front bumper side retainers	" "		$	53.80
				$	8,126.00
			Less 20%	$	1,625.20
				$	6,500.80

	SPECIAL NETT ITEMS			
1	Rear windscreen sealant	new	$	60.00 40
1	Rear bumper clip (1 set)	new	$	60.00 30
1	Rear bumper lower spoiler	one	$	650.00 ✓
1	Rear number plate	nn	$	50.00 X
1	Rear reverse sensor (1 set)	Shoked	$	380.00 200
1	Front bumper clip (1 set)	nn	$	60.00 X
1	Front bumper lower spoiler	One	$	650.00 ✓
1	Front number plate	nn	$	50.00 X
			$	1,960.00

S/N	LABOUR CHARGES			
1	To check wiring and reset headlamps focusing.	$		80.00
2	To remove, replaced damaged lamps and check up rear wiring.	$		80.00 30
3	To remove and refit inner garnishes.	$		150.00 60
4	To remove and refit rear reverse sensor.	$		150.00 50
5	To transfer rear tailgate mechanism and wiring assembly.	$		80.00 60
6	To remove and refit rear windscreen glass.	$		180.00 120
7	To remove, refit and replace exhaust silencer and mountings.	$	nn	120.00 X
8	To apply undercoating.	$		180.00 40
9	Panel beating.	$		1,800.00 600
10	To re-spray painting on the affected areas.	$		2,000.00 / 500
		$		4,820.00

GRAND TOTAL :	**$**	**13,280.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 20254
202
P - 1604.32
S.N - 1570.00
L - 2460
5634.32
202
4507