LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220 Business Reg. No.: 53387981K
Tel: 9101 7844 Fax: 6996 6442 Email: dylanlee.as @gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2012/FBF5169J/SM

ASSESSMENT FOR REPAIR : FBF5169J

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Handle bar	Bent	84.00	84.00
1 set	Handle end	Cut	40.00	40.00
1 pc	Brake lever	Usable	22.00	~
1 pair	Mirror	Grazed	90.00	90.00
1 pc	Headlight cover	Torn	74.00	74.00
1 pc	Headlight unit	Cracked	90.00	90.00
1 pc	Front center cover	Broken / Missing	82.00	82.00
1 pc	Front stay	Bent	48.00	48.00
1 pc	Horn	Cut	42.00	42.00
2 pcs	Fork assy @280.00	Badly Bent	560.00	560.00
1 pc	Fork under bracket	Bent	155.00	155.00
1 pc	Front fender	Torn	75.00	75.00
1 pc	Front wheel	Broken	370.00	370.00
1 pc	Front wheel axle	Bent	32.00	32.00
1 pc	Front brake disc	Bent	116.00	116.00
2 pcs	Leg shield complete @96.00	Broken	192.00	192.00
2 pcs	Front signal light @42.00	Broken / Cut	84.00	84.00
1 pc	Body frame top front cover	Broken	28.00	28.00
1 pc	Chassis top cover	Deformed	24.00	24.00
1 pc	Gear shift pedal	Usable	52.00	~
1 pc	Front footrest bar	Bent	64.00	64.00
1 set	Front footrest rubber	Cut	25.00	25.00
2 pcs	Rear cover @112.00	Grazed	Sn 224.00	224.00 X
1 pc	Muffler protector	Cut	82.00	82.00
			2,655.00	2,581.00
		Less 10%	265.50	258.10
			2,389.50	2,322.90
	Special Nett Items			
1 pc	Front number plate	Missing	20.00	18.00
1 set	Steering cone & bearing	Necessary	80.00	60.00
1 pc	Rear top box	Cut	280.00	250.00 200SN
1 pc	Rear rack	Bent	150.00	120.00 X
			530.00	448.00
	Total Parts		2,919.50	2,770.90
	Labour Charges			
1	Towing fee		80.00	60.00 35/.
2	Repair & straighten body frame		200.00	180.00 150/.
3	Spray painting for rear & affected body covers		400.00	350.00 300/.
4	Workmanship to renew damaged parts & repair affected areas		450.00	400.00 200/.
			1,130.00	990.00