FINAL COST OF REPAIR
(To be completed for only one type of item)

To:	From:	Ref	SAF 1222 - BB/1/1TPTBM)/D/CGTC/038/21
CHARLIE GTC, 1 TPT BN Unit	93FMD / MOS		

Description of Item:	MAN TGM 18.280 4X4			SAF 1222:	BB/1/1TPTBM)/D/CGTC/038/21
Part/Reg No:	**MID22023**	Original Value:	-	Date:	20 October 2021
				MO/MR:	8202694663/19611411
Quantity:	**01**	CE/Non CE:	-	Date:	16 December 2021
				Accident Job No:	8202694663/19611411
				Date:	16 December 2021

Description of Damages and Costs of Repairs:

S/N	Incident Repair	Man-hours
1)	Vehicle front bumper LH and panel bent inwards	35.00
1.1)	Remove and refit end panel to assist in repair	
1.2)	LH headlamp netting guard bent and missing (located inside cabin) Require to refit.	
1.2.1)	Netting guard all lock plate and its and its mounting screws	
2)	Cabin LH step well platform disloges - Require to remove and refit	
2.1)	Step well front portion slightly torn	
3)	Spray paint on above repaired areas	
4)	Conduct Road test after above repair	
5)	Diagnostic Fee for Equipment charged unde	

S/N	Materials Cost	Unit Price	Qty	COST
1)	LOCK PLATE	$6.94	4	$27.76
2)	OVAL HEAD SCREW	$1.22	8	$9.76
3)	HEX NUT	$1.18	8	$9.44
4)	PU-46168 BS381#DEEP BRONZE GREEN	$48.00	3	$144.00

Base/LEO Area Office's Assessment of Damages

Labour Charges @	$79.81	per hour X	34.00	hrs	= $2,793.35
Total Cost of Parts / Materials Used					= $190.96
Sub-contractor					= -
Assessment Fee					= $638.47
Towing Service					= $550.36
Total					**$4,173.14**

Estimated Time for Repair:	35 Hr

*Delete whichever is not applicable
FINAL COST OF REPAIR

HARI HARAN S/O ANBALAGAN

Digitally signed by HARI HARAN S/O ANBALAGAN
Date: 2022.01.24 12:45:08 +08'00'