COMFORT GRO ENGINEERING PTE LTD.

REPAIR ESTIMATE*

15.12.2021

VEHICLE NO SHD7109J

MAKE REG. 10.11.2016

MODEL HYU- I40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER BRACKET SIDE RH		$35.60	$35.60	n/c
10	REAR BUMPER CLIPS		$2.20	$22.00	n/c
1	REAR BUMPER			$553.00	DT
1	REAR BUMPER UNDER COVER			$228.00	n/ scr
1	REAR BUMPER REINFORCEMENT			$428.40	n xsvc
1	BOOTL LAMP RH			$565.60	~~ma~~ scr
1	BOOTLID CDRI			$52.40	n/
1	BOOTLID I-40 EMBLEM			$67.90	n/c
1	TAIL LAMP RH			$697.80	scr
	REAR FENDER LH			$2,171.40	xr
1	BOOTLID CHROME MOULDING			$85.00	n/c
1	REAR BUMPER REFLECTOR RH		$32.00	$32.00	Cu a
				$4,939.10	
	20.00%			$987.82	
	DISCOUNTED TOTAL			**$3,951.28**	
1	REAR BUMPER ADVERTISEMENT			$50.00	n/c
1	REAR FENDER RH ADVERTISEMENT			$100.00	n/c
1	REAR BUMPER MAT			$50.00	n/c
1	REVERSE SENSOR			$135.70	cut
				$322.13	
	Labour Charge			$600.00	280
	Panel Beating			$800.00	250
	Spray Painting Charge			$50.00	20
	Check lighting and wiring			$60.00	20
	Remove/refix reverse sensor			$60.00	20
	Tuff Kote			**$1,570.00**	
	TOTAL LABOUR				
	ESTIMATE TOTAL			**$5,843.41**	

Thevan 23.12.21

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thevan@chiangto.com
82235769
16/12/21 1600
CS b4 repaint photo
2 days up