威 利 摩 哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Not Authorised
L/Sup &
Resurvey After Paint
4-5days

10-JAN-2022

CHINA TAIPING Co (S) PL
105 Cecil Street
#18-00 The Octagon
Singapore 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SFG605Y
Accident involving vehicle no: SML9733S/SFG605Y
DOA: 06/01/2022 at NICOLL HIGHWAY TOWARDS KPE BEFORE KPE

Dear officer in charge
Estimate cost of repair for vehicle no: SML9733S
To supplied:

Description	Qty	Amount
Lid	1	R 655.80 X
Lid – Corolla emblem	1	42.35 —
Lid – Altis emblem	1	44.17 —
Lid – Toyota logo	1	50.25 —
Lid handle	1	Sn 298.20 X
Lid lock	1	382.00 ?
Lid reflector	2	Sn 590.40 X
Lid hinge	2	R 184.00 X
Boot weatherstrip	1	Rubber 166.40 50%
End panel	1	581.20 ?
End panel top garnish	1	Ref 229.40 —
Rear bumper	1	Bu 482.00 —
Rear bumper sponge	1	75.20 ?
Rear bumper retainer	1	Dif 92.33 —
Rear bumper reflector	2	Sn 113.80 X
Rear bumper enforcement	1	Bu 301.60 —
Tailamp NISCM	2	603.20 —
Parts		4,892,30
Parts less 25%		3,669.23

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Reverse sensor	DU 220.00 200sal
To remove damaged parts & attachments	
Wield and cut damaged panel	
Repair/reshape dented areas	
Straighten rear chassis when necessary	
Replace/align all parts into position	1100.00 1
To spray paint	1200.00 600

	6,189.23