Assg. Rec. By: GQ | Ref: CS/ICS22000567/Gvf3

ASSIGNMENT

From: Date:

Estimated Cost:

[OD] / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Ricardo Auto Centre

of

Insured:

Policy No. MPC21A00043604

Claims No. DMPC2200016H/CT

Sum Insured: Excess: 0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $92k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / [REV] / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFR8000G Yr Regn: 12 May 2017

Type [M.Car] M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA HARRIER c.c 1986

Colour MAROON A/C: Insured / Std / NI / NA

Sp.Reading 28464 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZSU600106307

Gen. Cond [Good] / Fair / Poor / Burnt

Steering: [Inorder] / Jammed / Leaked / Burnt or

Brake: [Inorder] / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / [STD A/Rim] or

Tyre Size: F: 235/55R18

R: //

[BS] / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 12/1/2022 D.O.I. 17-01-2022

Survey held at W/S 11:30

Des. of Damages : [Frt] / [Rear] / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/3/22	Informed Grace final fig $9183.10 (Red 3221.10, 25%)

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2) 14/3/22-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Invs ($)

[ ] : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format: Merimen

Lump Sum / UPD: $9183.10