REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
Parts:	143	MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	TTS Eurocars Pte Ltd/SKR8088U/07/03/2022 11:49	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	(1)	*RH SIDE SKIRT (250)	0.00	0.00	*420.00 F
2	1	(25)	*BRACKET (300) ?	0.00	0.00	*7.00 F
3	1	(26)	*BRACKET (310) ?	0.00	0.00	*7.00 F
4	1	(27)	*BRACKET (280) ?	0.00	0.00	*5.00 F
5	1		*BRACKET (270) ? XM	0.00	0.00	*6.00 F
6	1	(2)	*CLIPS(290)	0.00	0.00	*4.00 F
7	1	(3)	*CLIPS(295)	0.00	0.00	*4.00 F
8	1	(4)	*RH SIDE MIRROR	0.00	0.00	*645.00 F
9	1		*MOTOR (15) ? XM	0.00	0.00	*75.00 F
10	1	(5)	*LAMP (20)	0.00	0.00	*45.00 F
11	1		*MIRROR ? XM	0.00	0.00	*540.00 F
12	1	(28)	*GARNISH (160) ?	0.00	0.00	*25.00 F
13	1		*CAMERA (17) ? XM	0.00	0.00	*130.00 F
14	1	(6)	*COVER (120)	0.00	0.00	*105.00 F
15	1	(29)	*SIGNAL LAMP (140) ?	0.00	0.00	*105.00 F
16	1	(7)	*RHF DOOR	0.00	0.00	*1,250.00 F
17	1	(8)	*DOOR PILLAR GARNISH (160)	0.00	0.00	*65.00 F
18	1	(9)	*CLIPS (170)	0.00	0.00	*4.00 F
19	1	(10)	*WEATHERSTRIP (130)	0.00	0.00	*25.00 F
20	1	(30)	*DOOR HINGE TOP (30) ?	0.00	0.00	*90.00 F
21	1	(31)	*DOOR HINGE BOTTOM (70) ?	0.00	0.00	*95.00 F
22	1	(32)	*BRACKET (240) ?	0.00	0.00	*20.00 F
23	1	(33)	*BRACKET (220) ?	0.00	0.00	*20.00 F
24	1	(11)	*LOWER WEATHERSTRIP	0.00	0.00	*28.00 F
25	1	(12)	*TAPE FOAM (280)	0.00	0.00	*25.00 F
26	1	(13)	*WEATHERSTRIP DOOR (260)	0.00	0.00	*165.00 F
27	1	(34)	*DOOR CARRIER ?	0.00	0.00	*425.00 F
28	1	(35)	*WINDOW MOTOR (110) ?	0.00	0.00	*280.00 F
29	1	(36)	*BRACKET (15) ?	0.00	0.00	*4.00 F
30	1	(14)	*DOOR GLASS	0.00	0.00	*165.00 F
31	1	(37)	*CHROME (50) ?	0.00	0.00	*100.00 F
32	1	(15)	*WEATHERSTRIP (30)	0.00	0.00	*110.00 F
33	1	(16)	*OUTER GARNISH (70)	0.00	0.00	*70.00 F
34	1	(17)	*INNER GARNISH (90)	0.00	0.00	*40.00 F
35	1		*DOOR TRIM (70) ? XM	0.00	0.00	*920.00 F
36	1		*INNER TRIM (10) ? XM	0.00	0.00	*70.00 F
37	1		*SWITCH (100) ? XM	0.00	0.00	*215.00 F
38	1		*DOOR HANDLE (180) Repair	0.00	0.00	*230.00 F
39	1		*DOOR HANDLE COVER (190) repair	0.00	0.00	*8.00 F
40	1		*BRACKET (200) ? XM	0.00	0.00	*45.00 F
41	1		*HANDLE BRACKET (140) ? XM	0.00	0.00	*25.00 F
42	1	(38)	*DOOR LOCK (10) ?	0.00	0.00	*325.00 F
43	1	(39)	*BRACKET (70) ?	0.00	0.00	*14.00 F
44	1		*CABLE (120) ? XM	0.00	0.00	*18.00 F
45	1		*CABLE (130) ? XM	0.00	0.00	*10.00 F
46	1		*CABLE (90) ? XM	0.00	0.00	*20.00 F
47	1	(40)	*BRACKET (80) ?	0.00	0.00	*20.00 F

48	1		*CURTAIN AIR BAG	0.00	0.00	*560.00 F
49	1		*WEATHERSTRIP ON BODY (100)	0.00	0.00	*145.00 F
50	1		*CLIP FOR AIR BAG	0.00	0.00	*4.00 F
51	1		*TAPE RETAINER (902)	0.00	0.00	*48.00 F
52	1		*A PILLAR TRIM	0.00	0.00	*75.00 F
53	1		*RETAINER (30)	0.00	0.00	*8.00 F
54	1		*AIR BAG LOGO (20)	0.00	0.00	*15.00 F
55	1		*B PILLAR TOP TRIM	0.00	0.00	*115.00 F
56	1		*B PILLAR LOWER TRIM	0.00	0.00	*50.00 F
57	1		*CLIPS (220)	0.00	0.00	*4.00 F
58	1		*SEAT AIR BAG (370)	0.00	0.00	*550.00 F
59	1		*RETAINER	0.00	0.00	*4.00 F
60	1		*SEAT BACK COVER (340)	0.00	0.00	*265.00 F
61	1		*SEAT BELT (10)	0.00	0.00	*790.00 F
62	1		*BUCKLE (210)	0.00	0.00	*100.00 F
63	1		*ADJUSTOR	0.00	0.00	*65.00 F
64	1		*ROOF LINING (10)	0.00	0.00	*920.00 F
65	1		*FOAM (50)	0.00	0.00	*15.00 F
66	1		*AIR BAG CONTROL MODULE (10)	0.00	0.00	*590.00 F

F=Franchise part

Sub Total (S$)	**11,347.00**
+ Margin on L,N Items 25.00% (S$)	2,836.75
Total Parts (S$)	**14,183.75**

TTS Eurocars Pte Ltd/SKR8088U/07/03/2022 11:49. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
	Labour Items		
1	SUNDRIES	New	50 / ~~150.00~~
2	WIRING CONNECTION & CHECK	New	30 / ~~50.00~~
3	TUFF KOTE & SPRAY ANTI RUST PROOFING	New	30 / ~~50.00~~
4	LABOUR CHARGES TO DISMANTLE & REFIX FRONT DOOR, SIDE MIRROR, B PILLAR, ROCKER PANEL, SIDE SKIRT. TO REPAIR & ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION	New	~~1,000.00~~ 600 /
5	TO CONDUCT 4 WHEEL ALIGNMENT	New	^^X ~~60.00~~
6	TO REMOVE & REFIX FRONT DRIVER SEAT TO REPLACE AIR BAG	New	60 / ~~100.00~~
7	TO REMOVE & REFIX FRONT DASHBOARD TO REPLACE AIR BAG CONTROL UNIT	New	~~180.00~~ 150
8	TO REMOVE & REPLACE ROOF LINING TO REPLACE CURTAIN AIR BAG	New	150 / ~~480.00~~
9	TO TRANSFER & REPLACE FRONT RH DOOR COMPONENTS	New	/ ~~60.00~~
10	TO CARRY OUT SCN CODING FOR AIR BAG CONTROL MODULE photo?	New	250 / ~~550.00~~
11	TO REPLACE LEATHER ON DRIVER SEAT, TO INSTALL DRIVER SEAT AIR BAG	New	200 / ~~550.00~~
12	TO SPRAY PAINT FRONT RH DOOR, SIDE MIRROR, ROCKER PANEL, B PILLAR, SIDE SKIRT, FRONT RH FENDER, REAR RH DOOR & ALL OTHER ACCIDENT AFFECTED PORTION	New	980 / ~~1,200.00~~
13	TO REMOVE & REFIX CAMERA & SENSOR FOR PARK 360 SYSTEM, SCN CODING & TO CARRY OUT TEACH IN PROCESS OF THE PARKING SYSTEM photo.	New	200 / ~~550.00~~
14	TO CONDUCT ECU PROGRAMMING, CHECK & CLEAR FAULT CODES, RESTORE PROGRAMME MODULES photo?	New	100 / ~~200.00~~
		Gross Labour Cost (S$)	**5,100.00**

TTS Eurocars Pte Ltd/SKR8088U/07/03/2022 11:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
7 days
P/P
08/03/22 @1530
EXCESS: 3300
REVERT
Resurvey before paint

PRE INVOICE

HL ASSURANCE
11 KEPPEL ROAD
#11.01
SINGAPORE 089057

DOCUMENT NO : IN22-103598
DATE :24/05/2022

Vehicle No: SKR8088U
MERCEDES E200D
Mileage: 0000

Staff ID : EULINDRA
Account No : HLAS INSUR
JOB NO : T22-103598

No	Description	quantity U	Cost Price	Amount
1	RH SIDE SKIRT	1		$420.00
2	CLIPS (290)	3		$12.00
3	CLIPS (295)	3		$12.00
4	RH SIDE MIRROR	1		$645.00
5	LAMP (20)	1		$45.00
6	COVER (120)	1		$105.00
7	RHF DOOR	1		$1,250.00
8	DOOR PILLAR GARNISH	1		$65.00
9	CLIPS (170)	2		$8.00
10	WEATHERSTRIP (130)	1		$25.00
11	LOWER WEATHERSTRIP	1		$28.00
12	TAPE FOAM (280)	1		$25.00
13	WEATHERSTRIP SOOR (260)	1		$165.00
14	DOOR GLASS	1		$165.00
15	WEATHERSTRIP (30)	1		$110.00
16	OUTER GARNISH (70)	1		$70.00
17	INNER GARNISH (90)	1		$40.00
18	CURTAIN AIR BAG	1		$700.00
19	CLIP FOR AIR BAG	1		$4.00
20	TAPE RETAINER	1		$48.00
21	CLIPS (220)	2		$8.00
22	ROOF LINING	1		$920.00
23	FOAM (50)	1		$30.00
24	AIR BAG CONTROL MODULE	1		$590.00
25	BRACKET (300)	1		$7.00
26	BRACKET (310)	1		$7.00
27	BRACKET (280)	1		$7.00
28	GARNISH (160)	1		$25.00
29	SIGNAL LAMP (140)	1		$105.00
30	DOOR HINGE TOP	1		$90.00
31	DOOR HINGE BOTTOM	1		$95.00
32	BRACKET (240)	1		$20.00
33	BRACKET (220)	1		$20.00
34	DOOR CARRIER	1		$425.00
35	WINDOW MOTOR	1		$280.00
36	BRACKET (15)	1		$4.00
37	CHROME (50)	1		$70.00
38	DOOR LOCK (10)	1		$325.00

39	BRACKET (70)	1	$14.00
40	BRACKET (80)	1	$20.00
41	WEATHERSTRIP ON BODY	1	$145.00
42	RETAINER (30)	1	$8.00
43	AIR BAG LOGO (20)	1	$12.00
44	B PILLAR TOP TRIM	1	$115.00
45	NUT	1	$4.00
46	TRIM SEAT BASE	1	$265.00
47	SEAT BELT BUCKLE (210)	1	$100.00
48	LHR SEAT BELT	1	$300.00
49	CHASSIS STICKERS	1	$35.00
50	MIRROR SHELL	1	$120.00
51	DOOR TRIM STRIP	1	$85.00
52	ORNAMENTAL	1	$100.00
53	BEARING BRACKET	1	$100.00
54	SEAT AIRBAG	1	$550.00

Parts Total:	$8,943.00
10% on parts	$894.30
Sub-total	$9,837.30

SPECIAL NETT

1	Repair RHF seat belt	1	$135.00
2	Repair RHR seat belt	1	$135.00
		Total	$270.00

Labour

1	Sundries	1	$50.00
2	Wiring Connection and Check	1	$30.00
3	Tuff kote and spray anti rust proofing	1	$30.00
4	Labour charge to dismantle & refix front door, side mirror, B pillar, rocker panel, side skirt, To repair & adjust affected portion to specific dimension	1	$600.00
5	To remove & refix front driver seat to replace air bag	1	$60.00
6	To remove & refix front dashboard to replace air bag control unit	1	$150.00
7	To remove & replace roof lining to replace curtain air bag	1	$150.00
8	To transfer & replace front RH door components	1	$60.00
9	To carry out SCN coding for air bag control module	1	$250.00
10	To replace leather on driver seat, to install driver seat air bag	1	$200.00
11	To spray paint front RH door, side mirror, rocker panel, B pillar, side skirt, RHF fender, RHR door & all other accident affected portion	1	$980.00
12	To remove & refix camera & sensor for PARK 360 system, SCN coding & to carry out teach in	1	$200.00

	process of the parking system		
13	To conduct ECU programming, check and clear fault codes, restore programme modules	1	$100.00

Labour	$2,860.00
Subtotal	$12,967.30
7% GST	$907.71
Total	$13,875.01

* Acknowledgement by Customer *

I confirm that the goods stated in this invoice have been received by me in good working order and condition. I further confirm that all services and /or repair jobs Stated in this invoice are completed and done to my Satisfaction.

TTS EUROCARS PTE LTD

Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature

TTS EUROCARS pte ltd
Company Reg. No: 200413930H
383 Sin Ming Drive, TTS Centre, Singapore 575717 Ssles: +65 6842 2222 Admin: +65 6757 0122 Aft
Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65
For corporate, fleet & leasing enquiries, please contact +65 6462 1111 24-Hour Emergency Assistanc