ASS. BY: | REF: CS/HLA22003052/Dvy 3

ASSIGNMENT

From: Date:

Estim. Cost:

CD / TP / WS / TP RES / DD RES / EVA / INV / MV

To Inspect Vehicle No:

at W/O / Agents:

at

Insured

Policy No.

Claims to

Sum Insured: Excess:

(Client's Record)

Make / Model:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bal. of Market Value:

IDA.C Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Limit Sum: P/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SMX 4050Z Yr Regn: 2021 / Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Shuttle CC 1496

Colour Black A/C: Insured / Std / Rep / NA

Sp.Reading 19477 T/Radio: Insured / Std / Rep / NA

Eng/No: L15B6022382

C/No: GK82102048

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Broken / Jammed / Leaked / Burnt or

Brake: Broken / Jammed / Leaked / Burnt or

Modi: Nil / Sticker / STD A/Rim or

Tyre Size: F: 185/60R15

R: —11—

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YDKD or Bridgestone

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	31/03/2022	D.O.I.	02/04/2022

Survey held at Vin's Motor Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	HLA OD
	MV 90K
	LTA 36.5K
	HL 53.5K

Date/Time, File Pass to? 1) Date/Time, File Return to?

2)

☐ : Prel. Report

☐ : Final Report

Days Of Repair:

Reservey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **Hong Leong Assurance**
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057

Claim Details
Case Ref. No. : OD/032022/5329
Date : 31-03-2022
Accident Date : 30-03-2022

Vehicle Details
Make & Model : Honda SHUTTLE 1.5G CVT SENSING
Chassis No : GK82102048
Registration No : SMX4050Z

S/N	Description	Qty	Amount (S$)	
1	FRONT LH DOOR B/C	1.00	$550.00	✓
2	FRONT LH DOOR OUTER MOULDING H/C	1.00	$50.00	✓
3	FRONT LH DOOR OUTER HANDLE C/T	1.00	$240.00	✓
4	FRONT LH DOOR FRAME PILLAR STICKER H/C	1.00	$40.00	✓
5	FRONT LH DOOR RUBBER H/C	1.00	$30.00	✓
6	FRONT LH DOOR POWER WINDOW MOTOR WITH GEAR ~~R/I~~ ?	1.00	$140.00	?
7	FRONT LH DOOR INNER TRIMBOARD ?	1.00	$380.00	?
8	FRONT LH DOOR LOCK R/I	1.00	$150.00	X
9	LH SIDE SKIRT C/T	1.00	$250.00	✓
10	LH ROCKER PANEL R/R	1.00	$260.00	X
11	REAR LH DOOR B/C	1.00	$470.00	✓
12	REAR LH DOOR OUTER MOULDING H/C	1.00	$30.00	✓
13	REAR LH DOOR FRAME PILLAR STICKER H/C	1.00	$20.00	✓
14	REAR LH DOOR RUBBER H/C	1.00	$40.00	✓
15	REAR LH DOOR LOWER HINGE ?	1.00	$30.00	?
			$2,680.00	
	Margin: 5%		$134.00	
			$2,814.00	
16	TO REPAIR DAMAGES	1.00	~~$680.00~~	600/-
17	TO SPRAY PAINTING	1.00	~~$880.00~~	720/-

02/04/2022 @ 1045hr
Wkt Advised
P/PcA 5 days. 97237799
Photo after repr with Excess 325.00
damaged parts

Subtotal w/o GST: $4,374.00

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

LKK Advised