1 of 2 ? 100% Find | Next

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMO22001601/Uvy3-1

SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: [redacted] Date: [redacted] 18/04/2022 Code: SMO	
1.	**Policy Particulars :- (THIRD PARTY CLAIM)**		
Insured Veh.	[redacted] GBD 6194P	**Veh. Inspected**	[redacted] GBL 4280U
Policy No.		**Coverage ($)**	0.00
Claim No.	CMTD2200282/AGC	**Excess ($)**	0.00
Assign From	GRACE TEO	**Assign Date**	[redacted] 18/04/2022
2.	**Vehicle Particulars & Condition**		
Make & Model		**c.c**	0
Engine No.	HIDDEN	**Year of Reg.**	
Chassis No.		**Colour**	
Odometer	-	**Steering**	
Brakes		**Modification**	
General			
3.	**Conditions of Tyres**		

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.	**Description of Damages**		
5.	**General Information**		
Accident Date	19/01/2022	**Inspection Date**	21/02/2022
Survey held at	A S AUTO SERVICE NO 1 KAKI BUKIT #01-106 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.