TP Alg.
Ashes.

SNW1209J.

Honda Fit

GR11012328.

6.3K
06 days.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rear Number Plate Refund 30(SN)

Rear Number Plate Holder Refund 30(SN)

Rear Bumper Distorted 549.20 ~~859.10~~

Rear Bumper Clips. New 30(SN)

Rear Bumper Side Holder x02 New 29.1x2=58.20

Rear Bumper Reflector x02 New 65.9x2=131.80

Rear Bumper Impact Bracket x02 RH Dented 85x2=~~170~~ 85

Reverse Sensor Damaged ~~280(SN)~~ 200(SN)

Rear End Panel Dented 540.50

Rear End Panel Top Garnish Refund 241.40

Rear End Panel Top Garnish Clips. New 20(SN)

Rear End Panel Sealant New 60(SN)

Rear End Panel Buzzes Cancelled 139.40

SMW1209J

Rear End Panel Antenna Sensor	cw'd	189.40 ✓
Tail lamp x 02	LH cut, RH cw'd	550.5 x 2 = 1101 ✓
Tailgate	Dented	1035.60 ✓
Tailgate Lock	2nd	245.40 ✓
Tailgate Weatherstripe	cut	198.40 ✓
Tailgate Inner Trim Board	Dented	385.40 ✓
Tailgate Inner Trim Board Clips.	new	30(SN) ✓
Tailgate Reflector x 02	LH cut	450.1 x 2 = ~~900.20~~ 450.10
Tailgate Glass Moulding	NEW	188.40 ✓
Tailgate Glass Sealant.	NEW	60(SN) ✓
Fit Emblem.		48.90 ✓
Rear Camera.	new	480(SN) ✗
Rear Fender Inner Trim Board x 02	LH cw'd	395.6 x 2 = ~~791.20~~ 395.60
Rear Fender Inner Trim Board Clips.	new	60(SN) ✓
Rear Fender Inner Shield. LH	torn	102.40. ✓
Rear Fender Inner Shield Clips	new	20(SN) ✓
Spare Tyre Panel Top Cover	Dented	295.90 ✓

SMR1209J.

Tools Tray Sponge. torn		304.40 ✓
Rear Exhust Pipe	NH	694.80 ✗
Rear Exhust Pipe Mounting	NH	39.40 ✗
Rear Exhust Pipe Gasket.	NH	36.70 ✗
		655460 S.N: 480
		524368
		~~1200~~ 900
Panel Beating		~~1200~~ 800
Spray Painting		~~50~~ 30
Wiring		~~150~~ 60
To spray diff coat		~~100~~ 50
To remove reverse sensor		~~100~~ 50
To remove rear camera.		~~100~~ 50
To remove video recorder	2200	~~150~~ 60
To remove upholstery.		~~150~~ 80
To transfer tailgate fittings.		~~180~~ 120
To remove tailgate g/ss		150.✗
To remove exhust pipe.		

total: 7923.68

r/s: 6.3K

06 Days.