Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ 230 CE
Engine/Chassis No.: WDD1232432A250672
Date of accident:
Damaged area: O/S Rear

Not Authorise
LISmp @ 3400/h
Resurvey After Paint
5days

Date: 28/06/2022
Claim Type: TP
VRN: SMV9501S



List items

S/N	Parts description		QTY	UNIT PRICE	AMOUNT	
1	Rear bumper 1420	Buckled	1	$ 2,117.00	$ 2,117.00	✓
2	Rear fender o/s	R	1	$ 983.00	$ 983.00	✓
3	Rear fender chrome strip o/s	Buckled	1	$ 363.00	$ 363.00	✓
4	Rear fender inner panel o/s	R	1	$ 509.00	$ 509.00	X
5	Taillamp n/s 485	Buckled	1	$ 881.00	$ 881.00	✓
6	Taillamp base n/s	R	1	$ 234.00	$ 234.00	X
7	Taillamp lower chrome strip n/s	Out	1	$ 192.00	$ 192.00	✓
8	Taillamp weatherstrip n/s	Out	1	$ 85.00	$ 85.00	✓
9	End panel R		1	$ 739.00	$ 739.00	X
				Subtotal	$ 6,103.00	
				List discount	10.00%	
				Total	$ 5,492.70	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature by Repairer

Special nett items

No.	Parts description		QTY	UNIT PRICE	AMOUNT	
1	Rear bumper rivets	Nn	12	$ 5.50	$ 66.00	X
2	Rear fender inner panel sealant o/s	Nn	1	$ 100.00	$ 100.00	X
3	End panel sealant	Nn	1	$ 100.00	$ 100.00	X
4	Sundries	Nn	1	$ 50.00	$ 50.00	X
				Total	$ 316.00	

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	$ 1,200.00	7od
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	$ 100.00	2od
3	Supply spray paint material and necessary items to respray affected area / panel.	5	$ 1,000.00	4od
4	To rust proof all affected portions after repair.	0.5	$ 100.00	3od
		Total labour	$ 2,400.00	
		Estimate Grand Total	$ 8,208.70	