TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

TP Budget Direct.
Xiao Chen.

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER Not New	1	1083.00	X 1,083.00
FRONT BONNET Repair	1	2500.00	X 2,500.00
FRONT BONNET MECHANISM LOCK (LOWER) L/R } Not New	2	230.00	X 460.00
FRONT BONNET MECHANISM LOCK (UPPER) L/R	2	85.00	X 170.00
FRONT BUMPER Deformed	1	1400.00	✓ 1,400.00
FRONT BUMPER 'LOGO' EMBLEM New	1	67.75	✓ 67.75
FRONT BUMPER AIR DUCT L/R New	2	50.25	X 100.50
FRONT BUMPER FOGLAMP L/R Included.	2	480.00	✓ 960.00
FRONT BUMPER INNER GARNISH SUPPORT L/R Dented	2	54.45	✓ 108.90
FRONT BUMPER INNER SPONGE Included.	1	93.20	✓ 93.20
FRONT BUMPER LOWER CENTER GRILLE Dented	1	96.70	✓ 96.70
FRONT BUMPER LOWER GRILLE L/R Dented	2	195.50	✓ 391.00
FRONT BUMPER LOWER GRILLE MOULDING L/R Not New	2	33.60	X 67.20
FRONT BUMPER LOWER REINFORCEMENT Bent.	1	171.10	✓ 171.10
FRONT BUMPER PARKING SENSOR 2 pieces damaged	4	231.10	462.20 ~~924.40~~
FRONT BUMPER PARKING SENSOR 'O' RING } New	4	6.00	✓ 24.00
FRONT BUMPER PARKING SENSOR HOLDER	4	31.20	✓ 124.80
FRONT BUMPER PARKING SENSOR WIRE HARNESS Not New	1	223.75	X 223.75

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

FRONT BUMPER RUBBER SEAL Not New	1	41.30	X. 41.30
FRONT BUMPER SIDE RETAINER L/R Damaged.	2	16.20	✓ 32.40
FRONT BUMPER TOW HOOK COVER Not Nec	1	35.00	X. 35.00
FRONT BUMPER UPPER PANEL Not nec	1	171.55	X. 171.55
FRONT BUMPER UPPER REINFORCEMENT Bent.	1	668.10	✓ 668.10
FRONT BUMPER UPPER REINFORCEMENT BRACKET L/R Not Nec	2	56.55	X. 113.10
FRONT BUMPER WASHER COVER BRACKET L/R Damaged.	2	5.85	✓ 11.70
FRONT BUMPER WASHER COVER L/R Not Nec	2	34.60	X. 69.20
FRONT BUMPER WASHER NOZZLE L/R Damaged.	2	190.00	✓ ~~380.00~~
FRONT CROSS SUPPORT BRACKET L/R Dmd.	2	50.00	✓ 100.00
FRONT FENDER INNER TOP GARNISH COVER L/R torn	2	250.00	✓ 500.00
FRONT GRILLE L/R Lt.	2	190.00	✓ 380.00
FRONT HEADLAMP BRACKET L/R Cracked.	2	250.00	X. 500.00
FRONT HEADLAMP L/R Cracked.	2	4300.00	8,600.00
FRONT HEADLAMP SIDE BAR BRACKET L/R Not Nec.	2	17.95	X. 35.90
FRONT LH AIR CHANNEL Not Nec	1	31.10	X. 31.10
FRONT SEAT HEAD REST L/R Damaged.	2	793.50	✓ 1,587.00
FRONT SEAT HEAD REST SENSOR L/R Activated	2	193.35	✓ 386.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

FRONT TOP PANEL Dented.	1	395.00	✓ 395.00
RADIATOR AIR GUIDE Cracked	1	450.00	✓ 450.00
RADIATOR UPPER GARNISH Cracked.	1	105.00	✓ 105.00
RADIATOR UPPER PLUG CLIPS Not new	2	12.00	✗ 24.00
REAR BOOTLID Dented	1	1762.64	✓ 1,762.64
REAR BOOTLID '523I' EMBLEM } New	1	68.81	✓ 68.81
REAR BOOTLID 'LOGO' EMBLEM	1	78.00	✓ 78.00
REAR BOOTLID AUTO CLOSE MOTOR Not new	1	78.00	✓ 78.00
REAR BOOTLID MECHANISM LOCK Damaged	1	467.89	355 ~~467.89~~
REAR BOOTLID RUBBER GUIDE STOPPER L/R Not new	2	30.86	✗ 61.72
REAR BOOTLID SMART OPENER CONTROL UNIT Not New	1	490.93	✗ 490.93
REAR BOOTLID WEATHER STRIP Cut	1	193.66	✓ 193.66
REAR BRAKE CONTROL UNIT cracked.	1	1207.13	✓ 1,207.13
REAR BUMPER Distorted	1	1613.92	✓ 1,613.92
REAR BUMPER CENTER LOWER COVER Missing	1	142.00	✓ 142.00
REAR BUMPER INNER CENTER FRAME GARNISH Cracked	1	198.00	✓ 198.00
REAR BUMPER REINFORCEMENT Dented.	1	785.67	✓ 785.67
REAR BUMPER REINFORCEMENT ADAPTER GARNISH Cracked.	1	112.00	✓ 112.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

REAR BUMPER REVERSE SENSOR 2 pieces damaged.	4	260.54	521.08 ~~1,042.16~~
REAR BUMPER REVERSE SENSOR 'O' RING } Nec	4	11.00	✓ 44.00
REAR BUMPER REVERSE SENSOR HOLDER	4	28.00	✓ 112.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS Not nec	1	950.00	X. 950.00
REAR BUMPER RH LOWER COVER torn	1	92.00	✓ 92.00
REAR BUMPER SIDE BRACKET L/R Cracked.	2	151.53	✓ 303.06
REAR END PANEL Dented	1	1208.00	950 ✓ ~~1,208.00~~
REAR END PANEL LOWER PANEL Dented	1	294.30	✓ 294.30
REAR END PANEL TOP GARNISH Rebound.	1	109.50	✓ 109.50
REAR EXHAUST CHROME TAIL PIPE L/R Bent	2	143.61	✓ 287.22
REAR EXHAUST SILENCER ALUMINIUM HEAT SHIELD Not nec	1	143.16	X. 143.16
REAR EXHAUST SILENCER BOX Bent.	1	1678.10	1350 ✓ ~~1,678.10~~
REAR EXHAUST SILENCER GASKET KIT Not nec	1	66.00	X 66.00
REAR EXHAUST SILENCER RUBBER MOUNTING Not nec	2	33.00	X 66.00
REAR KEYLESS ANTENNA SENSOR cracked. 26340	1	105.98	✓ 105.98
REAR SPARE TYRE TOP BOARD COVER Not nec 23706	1	751.85	X. 751.85
REAR TAILLAMP L/R Cracked.	2	629.47	✓ 1,258.94

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

Subtotal before discount			39,355.99
Percentage discount 5%			1,967.80
Sub-total 1			37,388.19
FRONT BONNET INSULATOR MAT CLIPS - SET Not Nec	1	50.00	+ 50.00
FRONT BUMPER CLIPS - SET Nec	1	50.00	30 ~~50.00~~
FRONT BUMPER RIVET - SET Nec	1	50.00	30 ~~50.00~~
FRONT FENDER INNER TOP GARNISH CLIPS L/R - SET Nec	2	40.00	40. ~~80.00~~
FRONT NUMBER PLATE Bent	1	35.00	✓ 35.00
FRONT NUMBER PLATE HOLDER Defound	1	50.00	30 ~~50.00~~
RADIATOR COOLANT Not Nec	1	60.00	+. 60.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET Not Nec	1	50.00	+ 50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET Nec	1	30.00	10. ~~30.00~~
REAR END PANEL SEALANT Nec	1	100.00	60. ~~100.00~~
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET Not Nec	2	50.00	+. 100.00
REAR NUMBER PLATE Not Nec	1	35.00	+ 35.00
REAR NUMBER PLATE HOLDER Not Nec	1	50.00	+ 50.00
REAR TAILLAMP CLIPS L/R - SET Nec 255	2	20.00	20 ~~40.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHANG HEE TENG
BLK 336 TAMPINES ST 32 #04-486
SINGAPORE 520336

Contact : 97926188

TAX INVOICE

Repair Code : CLM15573
Date in : 27/06/2022
Vehicle Num. : SKB2345B
Model : B.M.W. 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Chassis/Eng# : WBAFP32060C865748/08777727N52B25AF

Subtotal before discount	780.00
Percentage discount 0%	0.00
Sub-total 2	780.00
Parts-total	**38,168.19**

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	150.00
To remove, change air bag, air-bag sensor, air-bag wire and resetting system.	300.00
To reset system after repair works	300.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,000.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	150.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,400.00
To apply anti-rust chemical on repaired and replaced panel.	150.00
Labour Total	**5,680.00**
Parts & Labour Total	**43,848.19**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature.***