HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	**Document No.**	: SQT22001939	**Page**	1
		Date	: 7. Jul 2022		
		Customer No.	: WZL009		
		Svc Advisor	: NG SIN HAI		
Registration No	: SCY8866Z	**Engine No**	: L15Z71000087		
Chassis No	: MRHRU1830FP000083	**Date | Time**	: 7. Jul 2022 1:34:39 PM		
Model	: HRV LX-SIN CVT YM 2015	**Surveyor Name**	:		
Owner's Name	: GOH SWEE CHIEW	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 7/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	110.00	30	110.00	7.70	117.70
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00	200	250.00	17.50	267.50
BOJSE	SEALANT FOR REAR END PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR LHR FENDER	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR TAILGATE	1	120.00		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	200	250.00	17.50	267.50
BMU30A	STRAIGHTEN ALIGN OR RENEW EXHAUST SYSTEM.(N)	1	650.00		650.00	45.50	695.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00		650.00	45.50	695.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	621.89	650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	550.00	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL.	1	6000.00	3,850.00	6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	2,120.00	3500.00	245.00	3745.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	580.00	450.00	580.00	40.60	620.60

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	**Document No.**	: SQT22001939	**Page**	2
		Date	: 7. Jul 2022		
		Customer No.	: WZL009		
		Svc Advisor	: NG SIN HAI		
Registration No	: SCY8866Z	**Engine No**	: L15Z71000087		
Chassis No	: MRHRU1830FP000083	**Date | Time**	: 7. Jul 2022 1:34:39 PM		
Model	: HRV LX-SIN CVT YM 2015	**Surveyor Name**	:		
Owner's Name	: GOH SWEE CHIEW	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 7/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00	450.00	650.00	45.50	695.50
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	36.40	556.40
BO-TOW	TOWING SERVICES (MBBS)	1	130.00		130.00	9.10	139.10
BOSUN	REMOVE AND VACUUM SHATTERED GLASSES	1	650.00	325.00	650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	450.00	650.00	45.50	695.50
				Sum Labor	**17790.00**	**1,245.30**	**19,035.30**
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X NN	1	45.00		45.00	3.15	48.15
39670-T7S-T01	SENSOR UNITPARKING X NN	1	291.30	25	218.47	15.29	233.76
39671-T7A-H00	BRACKETPARKING SENSOR UNIT X NN	1	4.70	25	3.52	0.25	3.77
39680-TV0-E01ZU	SENSOR ASSY PARKING T99 X NN	1	70.90	25	53.17	3.72	56.89
39680-TV0-E01C5	SENSOR ASSYPARKING X NN	1	93.70	25	70.27	4.92	75.19
39680-TV0-E11ZN	SENSOR ASSY PARKING T99 X NN	1	70.90	25	53.17	3.72	56.89
39680-TV0-E11ZN	SENSOR ASSY PARKING T99 X NN	1	70.90	25	53.17	3.72	56.89
39681-T7A-H01ZL	RETAINERPARKING SENSOR X NN	2	70.90	25	106.35	7.44	113.79
39683-T0A-Q01ZD	RETAINERPARKING SENSOR X NN	2	25.20	25	37.80	2.65	40.45
74940-TR0-003	BUZZER ASSYSMART X NN	1	64.10	25	48.07	3.36	51.43
33502-T7A-J01	LAMP UNITR BR	1	503.90	25 327.53	377.92	26.45	404.37
33552-T7A-J01	LAMP UNITL. CUT	1	503.90	25 327.53	377.92	26.45	404.37
34150-T7A-J01	LIGHT ASSY,R.LID BR	1	287.80	25 187.07	215.85	15.11	230.96
34155-T7A-J01	LIGHT ASSYL.LID BR	1	287.80	25 187.07	215.85	15.11	230.96
76700-T7A-003	MOTOR ASSYRR.WINDSHIELD WIPER X NN	1	121.30	25	90.97	6.37	97.34
76720-T7A-003	ARM,RR.WIPER CUT	1	45.40	25 29.51	34.05	2.38	36.43
76730-T7A-003	BLADEWINDSHIELD WIPER CUT	1	39.70	25 25.80	29.77	2.08	31.85
39530-T7M-H01	CAMERA ASSYRR.VIEW X NN	1	1110.30	25	832.72	58.29	891.01
68100-T8P-U10ZZ	TAILGATE COMP DD	1	910.50	25 591.82	682.87	47.80	730.67
68210-T5A-023ZZ	HINGE COMP,TAILGATE X NN	2	32.80	25	49.20	3.44	52.64
74440-T7A-003	WEATHERSTRIPTAILGATE CRU	1	105.20	25 68.38	78.90	5.52	84.42
74800-T7A-J01	LOCK ASSYTAILGATE X NN	1	90.10	25	67.57	4.73	72.30

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	**Document No.**	: SQT22001939	**Page**	3
		Date	: 7. Jul 2022		
		Customer No.	: WZL009		
		Svc Advisor	: NG SIN HAI		
Registration No	: SCY8866Z	**Engine No**	: L15Z71000087		
Chassis No	: MRHRU1830FP000083	**Date | Time**	: 7. Jul 2022 1:34:39 PM		
Model	: HRV LX-SIN CVT YM 2015	**Surveyor Name**	:		
Owner's Name	: GOH SWEE CHIEW	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 7/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER X NN	1	112.30	25	84.22	5.90	90.12
74820-T7J-H01	STAY ASSYR.TAILGATE OPEN X NN	1	115.50	25	86.62	6.06	92.68
74870-T7J-H01	STAY ASSYL.TAILGATE OPEN X NN	1	115.50	25	86.62	6.06	92.68
74899-T7A-003	DAMPERTAILGATE DYNAMIC X NN	1	69.40	25	52.05	3.64	55.69
74900-T8N-Q01ZA	GARNISH ASSYTAILGATE SPOILER X NN	1	138.40	25	103.80	7.27	111.07
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER X NN	1	102.00	25	76.50	5.36	81.86
84433-T8N-T01ZA	LINING ASSYTAILGATE UPPER X NN	1	26.90	25	20.17	1.41	21.58
84441-S2K-000ZB	POCKETTAILGATE PULL X NN	1	16.20	25	12.15	0.85	13.00
84485-T8N-T01ZA	LINING ASSYL.TAILGATE SIDE X NN	1	16.30	25	12.22	0.86	13.08
75722-T7W-A01	EMBLEMRR. ✓ NEC	1	15.20	25	9.88 ✓ 11.40	0.80	12.20
75725-T8N-T00	EMBLEM,RR. I-VTEC ✓ NEC	1	16.60	25	10.79 ✓ 12.45	0.87	13.32
73211-T8N-T01	GLASS SET,RR.WINDSHIELD ✓ BR	1	739.80	25	480.87 ✓ 554.85	38.84	593.69
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ✓ NEC	1	19.30	25	12.54 ✓ 14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 ✓ NEC	1	9.10	25	5.91 ✓ 6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER ✓ NEC	1	19.30	25	12.54 ✓ 14.47	1.01	15.48
76711-T6A-003	CAPPIVOT ✓ NEC	1	5.20	25	3.38 ✓ 3.90	0.27	4.17
91501-S70-003	FASTENER BW/SHIELD ✓ NEC	4	5.30	25	13.78 ✓ 15.90	1.11	17.01
91502-S70-003	FASTENER B ✓ NEC	2	5.50	25	7.15 ✓ 8.25	0.58	8.83
91536-SS0-J01	FASTENER AW/SHIELD ✓ NEC	2	3.80	25	4.94 ✓ 5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) X NN	2	60.00		120.00	8.40	128.40
34100-T5A-003	LIGHT ASSYLICENSE X NN	2	33.90	25	50.85	3.56	54.41
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE ✓ BR	1	189.80	25	123.37 ✓ 142.35	9.96	152.31
33505-T7A-J01	REFLECTOR ASSYR.RR. X NN	1	178.50	25	133.87	9.37	143.24
33555-T7A-J01	REFLECTOR ASSYL.RR. X NN	1	178.50	25	133.87	9.37	143.24
71501-T8N-T50	FACERR.BUMPER ✓ CRU	1	463.70	25	301.40 ✓ 347.77	24.34	372.11
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER ✓ CRU	1	95.30	25	61.94 ✓ 71.47	5.00	76.47
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER ✓ CRU	1	95.30	25	61.94 ✓ 71.47	5.00	76.47
71593-T7A-000	SPACER,R.RR.BUMPER SIDE ✓ BR	1	18.00	25	11.70 ✓ 13.50	0.95	14.45
71598-T7A-000	SPACER,L.RR.BUMPER SIDE ✓ BR	1	18.00	25	11.70 ✓ 13.50	0.95	14.45

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	**Document No.**	: SQT22001939	**Page**	4
		Date	: 7. Jul 2022		
		Customer No.	: WZL009		
		Svc Advisor	: NG SIN HAI		
Registration No	: SCY8866Z	**Engine No**	: L15Z71000087		
Chassis No	: MRHRU1830FP000083	**Date | Time**	: 7. Jul 2022 1:34:39 PM		
Model	: HRV LX-SIN CVT YM 2015	**Surveyor Name**	:		
Owner's Name	: GOH SWEE CHIEW	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 7/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90107-S9V-A01	BOLTRR.BUMPER STOPPER X NN	2	4.70	25	7.05	0.49	7.54
91505-TM8-003	CLIP,BUMPER ✓ NEC	8	2.30	25	11.96 ✓ 13.80	0.97	14.77
63320-T8N-T00ZZ	GUTTER COMPR.RR. X NN	1	163.90	25	122.92	8.60	131.52
63720-T8N-T00ZZ	GUTTER COMPL.RR. X NN	1	163.90	25	122.92	8.60	131.52
66100-T8N-T00ZZ	PANEL COMPRR.✓ DD	1	470.20	25	305.63 ✓ 352.65	24.69	377.34
84400-T7A-J01ZA	COVER COMPTONNEAU X NN	1	140.30	25	105.22	7.37	112.59
84610-T8N-T01ZA	BASE COMPR.TRUNK SIDE LINING X NN	1	149.70	25	112.27	7.86	120.13
84640-T8N-T01ZA	LINING ASSYRR.PANEL✓ CRU	1	66.60	25	43.29 ✓ 49.95	3.50	53.45
84660-T8N-T01ZA	BASE COMPL.TRUNK SIDE LINING X NN	1	149.70	25	112.27	7.86	120.13
04655-T7Y-T00ZZ	PANEL SET RR.FLOOR ~~X NN~~ DD	1	577.70	25	375.50 ✓ 433.27	30.33	463.60
65513-T7J-H00ZZ	STIFFENERRR.JACK UP ✓ NEC	1	44.50	25	28.92 ✓ 33.37	2.34	35.71
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR X NN	1	95.50	25	71.62	5.01	76.63
65770-T9A-T00ZZ	CROSSMEMBER COMP,RR.FLOOR RR✓ NEC	1	128.30	25	83.39 ✓ 96.22	6.74	102.96
72841-SH3-315	OILSHEET✓ NEC	3	43.40	25	28.21 ✓ 97.65	6.84	104.49
84521-T8N-T01ZA	BOARD ASSYTRUNK FLOOR X NN	1	106.00	25	79.50	5.57	85.07
84550-T7W-A00	BOX COMPTRUNK FLOOR X NN	1	134.70	25	101.02	7.07	108.09
74410-T7M-H01	PROTECTORR.RR.WHEEL ARCH X NN	1	172.10	25	129.07	9.03	138.10
74450-T7M-H01	PROTECTORL.RR.WHEEL ARCH✓ BR	1	172.10	25	111.86 ✓ 129.07	9.03	138.10
74552-T8R-T00	FENDERR.RR.INNER X NN	1	86.60	25	64.95	4.55	69.50
74592-T8R-T00	FENDERL.RR.INNER X NN	1	86.60	25	64.95	4.55	69.50
91501-T2A-003	CLIPINNER FENDER X NN	6	0.40	25	1.80	0.13	1.93
91501-TR0-003	CLIP,INNER FENDER X NN	8	2.80	25	16.80	1.18	17.98
				Sum Item	**8342.13**	**583.94**	**8,926.07**
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR ✓ NEC WINDSCREEN.	1	300.00	200.00	✓ 300.00	21.00	321.00
				Sum Ext. Service	**300.00**	**21.00**	**321.00**

Survey By _____

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	**Document No.**	: SQT22001939	**Page**	5
		Date	: 7. Jul 2022		
		Customer No.	: WZL009		
		Svc Advisor	: NG SIN HAI		
Registration No	: SCY8866Z	**Engine No**	: L15Z71000087		
Chassis No	: MRHRU1830FP000083	**Date | Time**	: 7. Jul 2022 1:34:39 PM		
Model	: HRV LX-SIN CVT YM 2015	**Surveyor Name**	:		
Owner's Name	: GOH SWEE CHIEW	**Survey Date**	:		
Ins Policy No.	:	**Authorisation Date**	:		
Date of Accident	: 7/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time				**Total Amount**	26,432.13	1,850.24	28,282.37
Excess				**Total (Inclusive of GST)**			**28,282.37**
Status							
Signature							

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0017415 / LONPAC	**Document No:**	SVO22030937
Chassis No:	MRHRU1830FP000083	**Printed By:**	SHNG
License No:	SCY8866Z	**Order Date:**	8. July 2022
Mileage:	86343	**Order Time:**	3:16:47 PM
Engine No:	L15Z71000087	**Service Advisor:**	NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY PART						
39680-TV0-E01C5	SENSOR ASSYPARKING (supp) BR	1	93.70 ✓	35	60.90	4.26	65.16
39681-T7A-H01ZB	RETAINER PARKING SENSOR (supp) NEC	2	70.90 ✓	35	92.17	6.45	98.62
74940-TR0-003	BUZZER ASSYSMART (supp) BR	1	64.10 ✓	35	41.66	2.92	44.58
33502-T7A-J01	LAMP UNITR.	1	503.90	35	327.53	22.93	350.46
33552-T7A-J01	LAMP UNITL.	1	503.90	35	327.53	22.93	350.46
34150-T7A-J01	LIGHT ASSY,R.LID	1	287.80	35	187.07	13.09	200.16
34155-T7A-J01	LIGHT ASSYL.LID	1	287.80	35	187.07	13.09	200.16
76720-T7A-003	ARM,RR.WIPER	1	45.40	35	29.51	2.07	31.58
76730-T7A-003	BLADEWINDSHIELD WIPER	1	39.70	35	25.80	1.81	27.61
68100-T8P-U10ZZ	TAILGATE COMP	1	910.50	35	591.82	41.43	633.25
74440-T7A-003	WEATHERSTRIPTAILGATE	1	105.20	35	68.38	4.79	73.17
75722-T7W-A01	EMBLEMRR.	1	15.20	35	9.88	0.69	10.57
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	16.60	35	10.79	0.76	11.55
73211-T8N-T02	GLASS SET,RR.WINDSHIELD	1	739.80	35	480.87	33.66	514.53
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5	1	9.10	35	5.91	0.41	6.32
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
76711-T6A-003	CAPPIVOT	1	5.20	35	3.38	0.24	3.62
91501-S70-003	FASTENER BW/SHIELD	4	5.30	35	13.78	0.96	14.74
91502-S70-003	FASTENER B	2	5.50	35	7.15	0.50	7.65
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	35	4.94	0.35	5.29
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE	1	189.80	35	123.37	8.64	132.01
71501-T8N-T50	FACERR.BUMPER	1	463.70	35	301.40	21.10	322.50
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	95.30	35	61.94	4.34	66.28
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	95.30	35	61.94	4.34	66.28
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	18.00	35	11.70	0.82	12.52
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	18.00	35	11.70	0.82	12.52
91505-TM8-003	CLIP,BUMPER	8	2.30	35	11.96	0.84	12.80
66100-T8N-T00ZZ	PANEL COMPRR.	1	470.20	35	305.63	21.39	327.02
84640-T8N-T01ZA	LINING ASSYRR.PANEL	1	66.60	35	43.29	3.03	46.32
04655-T7Y-T01ZZ	PANEL SET,RR.FLOOR	1	577.70	35	375.50	26.29	401.79
65513-T7J-H00ZZ	STIFFENERRR.JACK UP	1	44.50	35	28.92	2.02	30.94
65770-T9A-T00ZZ	CROSSMEMBER COMP,RR.FLOOR RR.	1	128.30	35	83.39	5.84	89.23
72841-SH3-315	OILSHEET	1	43.40	35	28.21	1.97	30.18
74450-T7M-H01	PROTECTORL.RR.WHEEL ARCH	1	172.10	35	111.86	7.83	119.69
38387-TZ5-A01	ANTENNA ASSYL.F. BR (SUPP)	1	63.20 ✓	25	47.40	3.32	50.72
			SUM PARTS:		**4,109.43**	**287.69**	**4,397.12**
BOSUN	1466	1	50.00		50.00	3.50	53.50