(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/EG/22W06603/Ucy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF1783C

at Workshop m/s Lin's Bros

of

Insured: YN 60663

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $40k.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 8 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted: LTA & 1799

Veh No: GBF1783C Yr Regn: 26/07/16

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or CA/

Make: Toyota hiace c.c 2982

Colour white/Black A/C: **Insured / Std / NI / NA**

Sp.Reading 99732 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JTFHT02PX00200301

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Austone.

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	08/07/22	D.O.I.	13/7/22

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Rear bpr.

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	Ok/10k.
2/8/22	L/S $8900 informed Susan. (Red $11,200.50 ; 55.7%)

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File **Return** to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)

Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: ERGO Insurance Pte Ltd
Addres: Motor Claims Department
8 Temasek Boulevard #04-01
Suntec Tower Three Singapore 038988

Ref Date: 08-07-2022
Ref No: GBF1783L220708
Vehicle No: GBF1783L
Model / Make: Toyota Hiace
Capacity: 2982 cc Van Turbo 4 DR Auto

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Tailgate Body 22	$ 2,051.60	1	$ 2,051.60		✓
2		Tailgate Lock 20/JM	$ 394.90	1	$ 394.90		✓
3		Tailgate Weatherstrip TW	$ 426.70	1	$ 426.70		✓
4		Tailgate Outer Garnish CR	$ 397.00	1	$ 397.00		✓
5		Tailgate Outer Garnish Accessories wraped	$ 400.00	1	$ 400.00	SN	380 S/N
6		Tailgate Inner Aluminium Board Bent	$ 450.00	1	$ 450.00	SN	400 S/N
7		Tailgate Inner Aluminium Board Clips 1 set NU	$ 65.00	1	$ 65.00	SN	45 S/N
8		Tailgate "Toyota" Motif NU	$ 70.50	1	$ 70.50		✓
9		Tailgate "70 KM/H" Sticker NU	$ 15.00	1	$ 15.00	SN	10 S/N
10		Tailgate "8 PAX" Sticker NU	$ 15.00	1	$ 15.00	SN	10 S/N
11		Number Plate "Metal" Bent	$ 35.00	1	$ 35.00	SN	20 S/N
12		Tailgate Windscreen Glass 12/1.10 shattered	$ 1,311.30	1	$ 1,311.30		✓
13		Tailgate Windscreen Glass Moulding NS	$ 219.00	1	$ 219.00		X
14		Tailgate Windscreen Glass Sealant NU	$ 50.00	1	$ 50.00	SN	40 S/N
15		Tail Lamp N/S 320	$ 386.40	2	$ 772.80		1 PC
16	1 set	Tail Lamp Outer Accessories N1 ~~CAR~~	$ 168.00	1	$ 168.00	SN	X
17		Bumper Accessories DIS	$ 1,250.00	1	$ 1,250.00	SN	1000 S/N
18		Bumper Clips 1 set NU	$ 65.00	1	$ 65.00	SN	50 S/N
19		Corner Panel Lh R	$ 165.80	1	$ 165.80		X
20	Rear	~~Corner Panel~~ Bracket Lh CRA	$ 31.50	1	$ 31.50		✓
21		Fender (Body Panel) Lh R	$ 1,718.50	1	$ 1,718.50		X
22		End Panel Outer Body 320	$ 566.10	1	$ 566.10		✓
23		End Panel Inner 8/45.10 Body 20	$ 936.20	1	$ 936.20		✓
24		End Panel Sealant NU	$ 50.00	1	$ 50.00	SN	✓ S/N
25		Top Wooden "Plywood" Board N	$ 450.00	1	$ 450.00	SN	X
26	Front	Bonnet R	$ 1,050.00	1	$ 1,050.00	SN	X
27		Bumper 20/TON	$ 796.80	1	$ 796.80		✓
28		Bumper Clips 1 set NU	$ 50.00	1	$ 50.00	SN	✓ S/N
29		Bumper Grille TON	$ 155.80	1	$ 155.80		✓
30		Grille sport CR	$ 680.00	1	$ 680.00	SN	500 S/N
31		Grille Clip 1 set N	$ 30.00	1	$ 30.00	SN	X
32		Aircon Condenser SU	$ 1,448.00	1	$ 1,448.00		X
33		Number Plate "Metal" NT	$ 35.00	1	$ 35.00	SN	X
		257					
		C/F Balance --->			$ 16,320.50		$ -

Submit to ins

Not Authorised
NU
13/7/22
I/S $8900
8 days.

Liu's Bro Auto Engrg Wks

Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: ERGO Insurance Pte Ltd
Address: Motor Claims Department
8 Temasek Boulevard #04-01
Suntec Tower Three Singapore 038988

Ref Date: 08-07-2022
Ref No: GBF1783L220708
Vehicle No: GBF1783L
Model / Make: Toyota Hiace
Capacity: 2982 cc Van Turbo 4 DR Auto

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
		B/F Balance --->		1	$ 16,320.50		$ -
29		To check all wiring & electrical component for proper function			$ 80.00		30
30		To remove & refix air con, re-fill air con gas & test for leakages			$ 300.00		100
32		Remove and refix rear tailgate components & wiper mechanism			$ 80.00		✓
33		Remove & reinstall Tailgate Glass to facilitate repairs			$ 120.00		✓
35		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 1,500.00		1300
36		To putty & spray painting & including touch up paint on accident affectecd areas			$ 1,600.00		1400
37		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 100.00		80

Total Parts & Labour of estimate for damaged vehicle	$ 20,100.50
Total amount in Lumpsum Basis for repaired vehicle	

SDL

Liu's Bro Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-7333.50
252
P-5500.12
S.N-2555
L-3110
11165.12
20%
8932.