LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT CS3/SMO21001620/Ucy3-1

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623

Ref: [redacted]

Date: [redacted] 19/07/2022

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	YP 3609U	**Veh. Inspected**	SMR 3153Z
	Policy No.	D20MTPCVE001918	**Coverage ($)**	0.00
	Claim No.	CMTD2100371/RUC	**Excess ($)**	0.00
	Assign From	[redacted]	**Assign Date**	[redacted] 19/07/2022

2. Vehicle Particulars & Condition

	Make & Model	TOYOTA HARRIER (A)	**c.c**	1998
	Engine No.	HIDDEN	**Year of Reg.**	2019
	Chassis No.	ASU600004745	**Colour**	BLUE / SILVER
	Odometer	22821 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	235/55 R19	MICHELIN	6 mm
	L/H Front Tyre	235/55 R19	MICHELIN	6 mm
	R/H Rear Tyre	235/55 R19	MICHELIN	6 mm
	L/H Rear Tyre	235/55 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.



5. General Information

	Accident Date	01/02/2021	**Inspect Date / Time**	03/02/2021 (11:15 AM)
	Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

Report Ref No. CS3/SMO21001620/Utd3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.