ASS. REC. BY: Tauffik   REF: INC

ASSIGNMENT

From: _____ Date: _____	Veh No: SH9943C Yr Regn: 2020 , March.
Estimated Cost: _____	Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: _____	Make: Hyundai long c.c 1580.
at Workshop m/s _____	Colour: Blue A/C: Insured / Std / NI / NA
of _____	Sp.Reading 192441 T/Radio: Insured / Std / NI / NA
Insured: _____	Eng/No: _____
Policy No. _____	C/No: KMHC851CVL4/90248
Claims No. _____	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: _____ Excess: _____	Steering: Inorder / Jammed / Leaked / Burnt or _____
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or _____
Make of Veh: _____	Modi: Nil / S/Rim / STD A/Rim or _____
	Tyre Size: F: 195/65R15
	R: " "

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or   Westlake.

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I. 26/8/22		

Bal. or Market Value: _____	Survey held at Comfort Lodging
IDAC Accident Rport: _____ Consistent? : Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____
GIA / PR Seen: _____ Consistent? : Yes or No	
Est. Repairs: _____ days Res.: Yes or No	
Lum Sum: _____ % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS WP	
Date: _____ Person Contacted: Lim TS Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? □ : Preli. Report	Days Of Repair: _____	Survey Fee:
□ : Final Report	Resurvey No. of Trip: _____	Transportation:
1) _____ Date/Time, File Return to?		S + RS.___SI
Add Fee: □ : Site Insp ($ _____)		Photos
2) _____	□ : Interview ($ _____)	Others
	□ : Tech. Invs ($ _____)	
Report Format : _____	□ : Weekend ($ _____)	
Lump Sum / LBH ($ _____)		TOTAL

COMFORTDELGRO ENGINEERING PTE LTD   LKK-

REPAIR ESTIMATE

FRONT

DATE: **10.08.2022**

MODEL: **Hyundai Ioniq**

VEHICLE NO.: **SH 9943C**

INSURANCE: **NTUC** CLS)

MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Radiator Grille	1		$ 1,409.10	fwg-
	Front Bumper Cover	1		$ 481.10	M-
	Front Bumper Moulding Centre Upper	1		$ 368.50	fwg-
	Front Bumper Grille LH / RH	2	$ 93.45	$ 186.90	?
	Front Bumper Towing Cover	1		$ 29.00	X
	Front Bumper Lower Moulding	1		$ 368.50	X
	Front Bumper Lower Stiffner	1		$ 285.10	?
	Front Bumper Lip	1		$ 35.10	X
	Front Bumper Bracket Top (LH/RH)	2	$ 35.00	$ 70.00	?
	Front Bumper Bracket (LH/RH)	2	$ 28.00	$ RHX 56.00	LHde -
	Front Bumper Clips 10 pcs	10	$ 2.20	$ 22.00	ner-
	Front Bumper Lower Grille	1		$ 365.30	X
	Headlamp Support Panel Assy	1		$ 949.30	?
	Headlamp LH / RH	2	$ 2,110.30	$ 4,220.60	Ewen-
	Day Light ,LH / RH	2	$ 642.50	$ 1,285.00	X
	Front Fender Shield LH	1		$ 164.70	?
	Flap Assy Active Air Upper LH	1		$ 824.60	?
	Actuator Active Air LH	1		$ 257.10	?
	Front Fender LH	1		$ 588.80	At-
	Bonnet	1		$ 2,253.80	At-
	Radiator Inverter	1		$ 884.80	?
	Radiator	1		$ 710.50	?
	Radiator Fan Motor	1		$ 576.00	?
	Radiator Fan	1		$ 375.10	?
	Air Con Condenser	1		$ 663.60	?
	SUB TOTAL			$ 17,430.50	
	LESS 20%			$ 3,486.10	
	DISCOUNTED TOTAL			**$ 13,944.40**	
	Front No.Plate With Trim Cover	1		$ 55.00	mis-
	LESS 10%			$ 5.50	
	NETT TOTAL			**$ 49.50**	
	SPARE PARTS TOTAL			**$ 13,993.90**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal mod (ification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan, HM 97495749
WIP 10/8/22 @ 430pm
L/S Resuny after repair
tanpHM c 3 days

				AMOUNT	
Labour Charge					
Panel Beating				$ 1,200.00	700
Spray Painting Charge				$ 1,200.00	750
Wiring Charge				$ 40.00	30
Tuff Kote				$ 40.00	30
R/I AIR CON CONDENSER ETC				$150.00	100% photo
TOWING FEE -				NIL	
TOTAL LABOUR				**$ 2,630.00**	
ESTIMATE TOTAL				**$ 16,623.90**	

LKK—

DATE: **10.08.2022**   *REAR*

MODEL: **Hyundai Ioniq**   INSURANCE: **NTUC** *(LHS)*

VEHICLE NO.: **SH 9943C**   MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		$ 459.40
	Rear Bumper Reinforcement	1		$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH	2	$ 138.10	$ 276.20
	Rear Bumper Side Brackets LH/RH	2	$ 55.80	$ 111.60
	Rear Bumper Centre Moulding Assy	1		$ 451.25
	Rear Bumper Lower Centre Moulding Assy	1		$ 155.00
	Rear Bumper Under Cover	1		$ 225.00
	Rear Bumper Cover Clips	10	$ 2.20	$ 22.00
	Rear Bumper Reflector Lamp LH/RH	2	$ 41.45	$ 82.90
	Rear Bumper Tow Cover	1		$ 98.80
	BootlLid Emblem – Hybrid	1		$ 24.30
	BootLid Emblem – Ioniq	1		$ 31.30
	BootLid Assy	1		$ 2,480.40
	BootlLid Lamp LH/RH	2	$ 794.40	$ 1,588.80
	Taillamp LH/RH	2	$ 870.40	$ 1,740.80
	Rear End Panel	1		$ 532.00
	Rear End Panel Garnish	1		$ 346.80
	Rear Smart Key Antenna	1		$ 40.50
	Rear Foglamp	1		$ 201.50
	SUB TOTAL			$ 9,263.35
	LESS 20%			$ 1,852.67
	DISCOUNTED TOTAL			$ 7,410.68
	BootlLid ComfortDelGro	1		$ 35.00
	BootLid 65521111	1		$ 35.00
	BootLid APPS	1		$ 40.00
	Reverse Sensors	1		$ 180.00
	Rear No.Plate With Trim Cover	1		$ 55.00
	Rear Windscreen Sealant	2	$ 46.00	$ 92.00
	S/NETT SUB			$ 437.00
	LESS 10%			$ 43.70
	S/NETT TOTAL			$ 393.30
	Rear Bumper Mat	1		$ 50.00	S/NETT
	SPARE PARTS TOTAL			$ 7,853.98

(boxed annotation, partly obscured)
LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(handwritten left margin)
Tanjihin 97415741
WP 10/8/22 @ 430pm
L/s Missing after repair
tampil @ LKK auto wh
3 days

Labour Charge

	Panel Beating			$ 1,200.00
	Spray Painting Charge			$ 1,200.00
	Remove/Refix Reverse Sensor			$ 120.00
	Remove/Refix Rear Windscreen Glasses			$ 250.00
	TOTAL LABOUR			$ 2,770.00
	ESTIMATE TOTAL			$ 10,623.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline +65 6383 6280 Facsimile +65 6280 9755
Service Centres
205 Braddell Road Singapore 579701   59 Loyang Drive Singapore 508969
45 Pandan Road Singapore 609286   383 Sin Ming Drive Singapore 5757
7 Sungei Kadut Way Singapore 728791   320 Ubi Road 3 Singapore 408649

6553 1111
SPARK Assist
Recovery · Towing · Accident

Appointed Partners

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 10 / 08 / 22   Time Received: 0925

2. ☐ New   ☐ SPARK Kakis

Name of Customer : Mr. Teng

Contact No. : 96897487

Vehicle No. : ✓ SH9943C

Make / Model / Colour : Ioniq

Email :

3. Vehicle Type:
- ☐ Private
- ☑ Taxi (CTPL/CCPL)
- ☐ Fleet
- ☐ STK (Boon Lay)

5. Nature of Service:
- ☐ Jumpstart
- ☑ Recovery
- ☐ Change Tyre / Battery

4. Type of Towing:
- ☐ Normal Tow
- ☑ King Dolly
- ☐ Flat Bed
- ☐ Crane-up

6. Parts Replaced/Remarks:

7. Location: Jln Ahmad Ibrahim

9. Preferred Workshop:
- ☐ Braddell
- ☑ Loyang
- ☐ Pandan
- ☐ Sin Ming
- ☐ Sungei Kadut
- ☐ Ubi
- ☐ Komoco (UBI / Leng Kee)
- ☐ Cycle & Carriage (PD)
- ☐ Others:

8. Vehicle Tow - In Workshop:
- ☐ Smoky Exhaust
- ☐ Overheating
- ☐ Brake Faulty
- ☐ Starting Problem
- ☑ Accident
- ☐ Return Taxi
- ☐ Wheel Jammed
- ☐ Steering Faulty
- ☐ Alternator Faulty
- ☐ Loss Power
- ☐ Engine Stalled

10. Odometer Reading :

Fuel Level : | F | 1/4 | 1/2 | 3/4 | E |

11. Radio / CD Player
- ☐ OK
- ☐ Faulty
- ☑ Not tested

FRONT

LEFTSIDE   RIGHTSIDE

REAR

\#: Cracked   X : Dented
/ : Scatched   O : Missing

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☑ QA ☐ GAO ☐ OTHERS

Name of Driver : Bee

Vehicle No. : YP76HF6L

Time Dispatch : 0925

Time of Arrival : 0955

Time Completed : 1025

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

10 / 08 / 22
Date

0955
Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY

COMFORTDELGRO
NGINEERING

Date/Time: 10.08.2022 13:46   Page : 1

JOB CARD Sales Order: 4522954   JC N 305526042

m: ARC Repair TP(CLSO)1

OMER	REGN NO.: SH 9943C
IS **COMFORT TRANSPORTATION PTE LTD**	MILEAGE
OMER NO. 7010045	MAKE : HYUNDAI
ESS 383 SIN MING DRIVE	FUEL E...........1/2...........F
Singapore SINGAPORE 575717	MODEL IONIQ(G3)
(R) 65508755 (O)	DATE/TIME IN 10.08.2022 08:15
(P)	YR OF MANU. 18.03.2020
	TARGET DATE
DUNT CARD NO.	CHASSIS CODE KMHC851CVLU190248
	COMPLETION DATE/TIME:

ident Date: 10.08.2022
URE: 3P 10.08.2022

JOB DESCRIPTION

O	LABOR CODE	DESCRIPTION
010	PB	PANEL BEATING-SH 9943C-TP

FRONT
LEFT SIDE   RIGHT SIDE
REAR

ED & PASSED OUT BY: _____

_____
SERVICE ADVISOR

_____
CUSTOMER'S SIGNATURE

igement Slip

Exit Pass

SH 9943C   LIMTS

Vehicle No.:
SH 9943C

ervice Advisor   Signature/Date

Name of Service Advisor   Date

ied to Service Reception upon collection

To be kept by Security Guard