GQ CS/ASM22007825/Gcy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / RS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s: ERZAT LEE MOTOR

of

Insured: 9898 3441 Erzat

Policy No: 8952 1180

Claims No.: Hidayah

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $ 6,800.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBL8873H Yr Regn: 03 May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CBF190X c.c 184

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 9645 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LALPJL702H3017415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-17

R: 150/60-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	16-08-2022

Survey held at W/S 2:30PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/3/23	Finalised LS $900/-; 2 days with Hidayah. (Red. $2150/-, 70%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weld and ($)

Survey Fee:

Transportation: S + RS SI

Photos

Other:

TOTAL

Report to Fin. Dept: TP

Total Claim / LS: $900/-

李 汽 车 贸 易 GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800
REG. NO. 201918537M
EMAIL : enquiry@erzatleemotor.com
Office : 69661751

ESTIMATE COST OF REPAIR

Date: 15-Aug-22 Estimate no. 1144

Plate No. FBL8873H
Model. HONDA FIGHAWK

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE ($)	REMARK	PRICE ($)
1	FORK ALIGNMENT ~~X~~ X NN	$ 300.00	X	
2	HANDLE BAR ~~X~~ X NN	$ 250.00	X	
3	HANDLE BAR END X NN	$ 120.00	X	
4	MIRROR SET — Cut	$ 120.00	80	
5	HANDLE GUIDE — Cut	$ 150.00	120	
6	CRASH BAR X Replace	$ 320.00	X	
7	REAR KEY LOCK — MIS	$ 180.00	120	
8	REAR FAIRING COVER — Cut	$ 250.00	—	
9	REAR NUMBER PLATE X Repair	$ 30.00	X	
10	REAR BOX — MIS	$ 380.00	280	
11	FRONT LEFT FOOTREST — } Cut	$ 150.00	60	
12	REAR LEFT FOOTREST —	$ 120.00	60	
13	REAR SIGNAL LIGHT —	$ 180.00	90	
14	LABOUR	$ 500.00	200	

2 Days.
Company repair
After repair photos.
Guo Qiang
82880282
16/8/2022

Klan

LKK Auto Consultants hence notify
the Repairer of the following:
• To resume
•
•
•
•
•
Acknowledge
Signature:
Date:

Less 10%	$	305.00	
Sub Total :	$	2,745.00	3050
GST 7%	$	192.15	
Total:	$	2,937.15	

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*
This is computer generated no signature is required.