SM AUTOMOTIVE

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883
Accident dat : 12/08/2022

13/08/2022

TP ALG.
Asher.

Estimated repair cost for vehicle no: SKH7491Y MERCEDES BENZ C180K
CHASSIS: WDD2040462A136084 (2008)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER *Rebuild*	$1,201.00	$1,201.00
2	1	FRONT BUMPER REINFORCEMENT *xte nn*	$587.00	$587.00
3	1	FRONT BUMPER SPONGE *New*	$344.00	$344.00
4	1	FRONT BUMPER SIDE RETAINER LH *LH Bayd*	$84.00	$84.00
5	1	FRONT BUMPER CENTER BRACKET	$87.00	$87.00
6	1	FRONT BUMPER CHROME MOUDLING LH	$64.00	$64.00
7	1	FRONT BUMPER FOG LAMP LH *new*	$434.00	$434.00
8	1	FRONT BUMPER FOG LAMP OUTER GARNISH LH *New*	$324.00	$324.00
9	1	FRONT BUMPER LOWER GRILLE *New*	$198.00	$198.00
10	1	FRONT BUMPER CENTER MOULDING *New*	$164.00	$164.00
11	1	FRONT GRILLE	$695.00	$695.00
12	1	FRONT GRILLE LOGO *New*	$143.00	$143.00
13	1	FRONT GRILLE LOGO BASE	$215.00	$215.00
14	1	BONNET *New*	$1,268.00	$1,268.00
15	1	BONNET HINGE LH	$174.00	$174.00
16	1	FRONT HEADLAMP LH *cut*	$1,045.00	$1,045.00
17	1	FRONT HEADLAMP LOWER BARCKET LH *new*	$189.00	$189.00
18	1	FRONT FENDER LH *Dented*	$652.00	$652.00
19	1	FRONT FENDER INNER COWLING LH *torn*	$187.00	$187.00
20	1	FRONT LOWER ARM (REAR) LH *Bent*	$669.00	$669.00
21	1	FRONT LOWER ARM (FRONT) LH	$774.00	$774.00
22	1	FRONT UPPER ARM LH *Bent*	$696.00	$696.00
23	1	FORNT KNUCKLER ARM LH *Bend*	$689.00	$689.00
24	1	FRONT KNUCKLER ARM BEARING LH *Bend*	$460.00	$460.00
25	1	FRONT SHOCK ABSORBER LH *Bent*	$672.00	$672.00

7129
6416·10

TOTAL :	**$12,015.00**
LESS 10 %	**$1,201.50**
SUB-TOTAL :	**$10,813.50**

SKH7491Y MERCEDES BENZ C180K

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT SPORT RIM LH *Cut*	$900.00	$900.00 *500*
2	1	FRONT TYRE LH *New*	$380.00	$380.00 *✓*
3	1	FRONT BUMPER CLIPS *New New*	$80.00	$80.00 *30*
4	1	FRONT FENDER INNER COWLING CLIPS LH *New*	$60.00	$60.00 *30*

560.

TOTAL: **$1,420.00**

TOTAL PARTS : **$12,233.50**

Labour charges

1	LABOUR FOR PANEL BEATING	*600*	$1,400.00
2	LABOUR FOR SPRAYPAINTING	*500*	$1,200.00
3	WIRING CHECK	*30*	$80.00
4	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE	*300*	$400.00
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	*50*	$300.00
6	TO CONDUCT WHEEL ALIGNMENT	*80*	$150.00

1560

$3,530.00

Total:- **$15,763.50**

Adrian Lim
L/S 15/08/22.

06 Days.

Supplementary: 3638-70

Total: 12174.80

L/S: 8.8k. (Nett Value)

8.8K

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
Email: SM_AUTOMOTIVE@HOTMAIL.COM
Tel: (65) 6747 9241   Fax: (65) 6741 7276
RCB No: 53231488C   GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6   16/08/2022
 # 01-43
Singapore 417883
Accident dat : 12/08/2022
Estimated repair cost for vehicle no: SKH7491Y MERCEDES BENZ C180K
CHASSIS: WDD2040462A136084 (2008)
SUPPLEMENTARY

S/N	Qty	Items		U/price	Amount
1	1	STEERING RACK & PINION	Bent	$3,761.00	$3,761.00
2	1	ANTI ROLL BAR	New	$486.00	$486.00
3	1	LH ANTI ROLL BAR LINK	Bent	$282.00	$282.00

TOTAL :	$4,529.00
LESS 10 %	$452.90
SUB-TOTAL :	$4,076.10

4043

3638.70

Adrin
16/08/22