# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref:	CS3/ASM22007871/Tcy3m4
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date:	11/11/2022
ATTN: KHOR SAW THENG	Code:	ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 4096Y	Veh. Inspected	FBP 8032Y
Policy No.	VFX/P2419138	Coverage ($)	0.00
Claim No.	S2M04933	Excess ($)	0.00
Assign From	KHOR SAW THENG	Assign Date	17/08/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA CB150R	c.c	149
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MLHKC2881J5016571	Colour	GREEN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 R17	PIRELLI	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & N/S BODY.

5. General Information

Accident Date	16/08/2022	Inspect Date / Time	17/08/2022 (04:06 PM)
Survey held at	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**6 Working Days**

Report Ref No. CS3/ASM22007871/Tcy3m4

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser