# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R  GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4529E

| Qty | Description of Parts | Condition | Estimate By Workshop ($)) | Our Adjusted ($) |
|---|---|---|---|---|
| | **REPLACEMENT OF PARTS** | | | |
| 1 | DOOR RH | BENT | 1,334.00 | 1,334.00 |
| 2 | DOOR HINGE RH @$121.00 | DISTORTED | 242.00 | 242.00 |
| 1 | DOOR CHECKER RH | SERVICEABLE | 150.00 | - |
| 1 | DOOR LOCK RH | DENTED | 286.00 | 286.00 |
| 1 | DOOR OUTER HANDLE RH | SERVICEABLE | 185.00 | - |
| 1 | DOOR INNER TRIMBOARD RH | MTG CRACKED | 465.00 | 465.00 |
| 1 | DOOR WINDOW CHANNEL RH | SERVICEABLE | 115.00 | - |
| 1 | DOOR STEP PANEL RH | TO REPAIR SEE LABOUR | 342.00 | - |
| 1 | DOOR STEP GARNISH RH | SERVICEABLE | 151.00 | - |
| 1 | FRONT BUMPER | SERVICEABLE | 1,086.00 | - |
| | LESS 25% DISCOUNT | | -1,089.00 | -581.75 |
| | | | 3,267.00 | 1,745.25 |
| | | | | |
| 1 | DOOR WEATHERSTRIP RH (50%) (SN) | CUT | 186.00 | 93.00 |
| | LESS 25% DISCOUNT | | -46.50 | - |
| | | | 139.50 | 93.00 |
| | **SPECIAL NETT ITEMS** | | | |
| 8 | DOOR INNER TRIMBOARD CLIPS RH @$5.50 (SN) | NECESSARY | 44.00 | 44.00 |
| 6 | DOOR STEP GARNISH CLIPS RH @$5.50  (SN) | NOT NECESSARY | 33.00 | - |
| 1 | DOOR COMPANY STICKER  (SN) | NECESSARY | 25.00 | 25.00 |
| | | | 102.00 | 69.00 |
| | **LABOUR** | | | |
| | LABOUR TO REMOVE & REPLACE AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF DOOR STEP PANEL RH . | | 800.00 | 400.00 |
| | SPRAY PAINT ON AFFECTED AREAS . | | 500.00 | 360.00 |
| | TO APPLY ANTI RUST COATING ON AFFECTED AREAS . | | 100.00 | 30.00 |
| | TO REMOVE & REFIT DOOR COMPONENTS. | | 100.00 | 60.00 |
| | LABOUR CHARGE TO CHECK WIRING AND LIGHTINGS. | | 50.00 | 20.00 |

Report Ref No. CS/AGI22007985/Kvy3q2

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R  GST Reg. No. 19-9607198-R

| Qty | Description of Parts | Condition | Estimate By Workshop ($)) | Our Adjusted ($) |
|---|---|---|---|---|
| | TO REDRAW DOOR LOGO. | | 200.00 | 80.00 |
| | | | 1,750.00 | 950.00 |
| | **GRAND TOTAL** | | **5,258.50** | **2,857.25** |

| | | | |
|---|---|---|---|
| **RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)** | | | **2,250.00** |

Report Ref No. CS/AGI22007985/Kvy3q2

*KSC*

**KONG SENG CHEONG**

**Licensed Appraiser**