## REPAIR DETAILS

### Reference

| | | |
|---|---|---|
| **Part Source:** | MRM-SG | Version: 1.0 (Last Synchronised: 31 Aug 2022) |
| **Parts:** | 143 | TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| **Labour:** | Repairer's | (Price-denominated Standard List) |
| **Print Code:** | (Unsubmitted, no print-code for SDK8800A) | |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. | |

### Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|---|---|---|---|---|---|---|
| 1 | 1 | | *LH WING MIRROR ASSY | 25.00 | 0.00 | *1,374.90 FL |
| 2 | 1 | | *FRT RH DOOR 1774.40 | 25.00 | 0.00 | *1,774.10 FL |
| 3 | 1 | | *FRT RH DOOR HINGE TOP | 25.00 | 0.00 | *103.10 FL |
| 4 | 1 | | *FRT RH DOOR HINGE LOWER | 25.00 | 0.00 | *117.60 FL |
| 5 | 1 | | *FT RH DOOR CHECKER | 25.00 | 0.00 | *195.20 FL |
| 6 | 1 | | *FRT RH DOOR WINDOW REGULATOR | 25.00 | 0.00 | *293.50 FL |
| 7 | 1 | | *FRT RH DOOR WINDOW MOULDING (CHROME) | 25.00 | 0.00 | *121.10 FL |
| 8 | 1 | | *FRT RH DOOR FRAME MOULDING (BLACK) | 25.00 | 0.00 | *83.50 FL |
| 9 | 1 | | *FRT RH DOOR WHEATHERSTRIP | 25.00 | 0.00 | *245.50 FL |
| 10 | 1 | | *FRT RH DOOR LOCK MECHANISM | 25.00 | 0.00 | *639.60 |
| 11 | 1 | | *FRT RH DOOR GLASS | 25.00 | 0.00 | *909.20 FL |
| 12 | 1 | | *FRT DOOR HANDLE SEAL 1 | 25.00 | 0.00 | *38.20 FL |
| 13 | 1 | | *FRT DOOR HANDLE SEAL 2 | 25.00 | 0.00 | *38.20 FL |
| 14 | 1 | | *FRT RH DOOR HANDLE INNER BASE | 25.00 | 0.00 | *224.70 FL |
| 15 | 1 | | *FRT RH DOOR HANDLE SWITCH | 25.00 | 0.00 | *44.80 FL |
| 16 | 1 | | *FRT DOOR INNER TRIM | 25.00 | 0.00 | *1,855.90 FL |
| 17 | 1 | | *RH CENTER PILLAR OUTER | 25.00 | 0.00 | *343.00 FL |
| 18 | 1 | | *RH ROCKER PANEL GARNISH Dd/Dr.r | 25.00 | 0.00 | *633.30 FL |
| 19 | 1 | | *REAR RH DOOR 1597.40 | 25.00 | 0.00 | *1,597.40 FL |
| 20 | 1 | | *RER RH DOOR HINGE TOP | 25.00 | 0.00 | *103.10 FL |
| 21 | 1 | | *REAR RH DOOR HINGE LOWER | 25.00 | 0.00 | *103.10 FL |
| 22 | 1 | | *REAR RH DOOR CHECKER | 25.00 | 0.00 | *233.70 FL |
| 23 | 1 | | *REAR RH DOOR WINDOW MOULDING (CHROME) | 25.00 | 0.00 | *97.90 FL |
| 24 | 1 | | *REAR RH DOOR FRAME MOULDING (BLACK) | 25.00 | 0.00 | *83.50 FL |
| 25 | 1 | | *REAR DOOR WHEATHERSTRIP | 25.00 | 0.00 | *217.30 FL |
| 26 | 1 | | *REAR DOOR LOCK | 25.00 | 0.00 | *595.70 FL |
| 27 | 1 | | *REAR DOOR GLASS | 25.00 | 0.00 | *443.30 FL |
| 28 | 1 | | *REAR DOOR WINDOW REGULATOR | 25.00 | 0.00 | *289.30 FL |
| 29 | 1 | | *REAR DOOR RUBBER | 25.00 | 0.00 | *79.50 FL |
| 30 | 1 | | *DRIVER SEAT BACKREST CUSHION COVER | 25.00 | 0.00 | 450 - |
| 31 | 1 | | *DRIVER SEAT BACKREST CUSHION SPONGE | 25.00 | 0.00 | 100 - |
| 32 | 1 | | *DRIVER SEAT AIRBAG 2867.40 | 25.00 | 0.00 | *3,039.50 |
| 33 | 1 | | *DRIVER SEATBELT | 25.00 | 0.00 | *1,050.40 |
| 34 | 1 | | *ROOF LINING 1389.20 | 25.00 | 0.00 | 2,140.50 |
| 35 | 1 | | *RH ROOF TOOP AIRBAG | 25.00 | 0.00 | 2318.90 |
| 36 | 1 | | *AIRBAG CONTROL UNIT 1688.20 | 25.00 | 0.00 | *1,864.90 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|---|---|
| **Sub Total (S$)** | 15,446.30 | **18,834.00** |
| **- List Item Discount on L Items (S$)** | | 4,708.50 |
| **Total Parts (S$)** | | **14,125.50** |

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|---|---|---|---|
| **Miscellaneous Items** | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| | | Sub Total (S$) | 11.00 |

## Estimates on Labour

| No | Particulars | Lab.Type | | Amount |
|---|---|---|---|---|
| **Labour Items** | | | | |
| 1 | To knock & straighten on accident area, to remove & refit RIGHT damage parts | New | 7od | 1,000.00 |
| 2 | To putty & respray on frt rh door, rear rh door, rh center pillar, rh rocker panel garnish, rh roof top pillar | New | 9od | 1,000.00 |
| 3 | To repair rh roof top pillar | New | 2od | 400.00 |
| 4 | To check wiring | New | 2d | 100.00 |
| 5 | To remove & refit FRT RH Door trim, door glass, window regulator, door lock to assist work load. | New | | 80.00 |
| 6 | To remove & refit REAR RH Door trim, door glass, window regulator, door lock to assist work load. | New | | 80.00 |
| 7 | To refit airbag system | New | 25d | 400.00 |
| 8 | To reset airbag control unit | New | | 200.00 |
| 9 | To remove & refit roof lining, inner trim to assist work load | New | 12od | 200.00 |
| 10 | To remove & refit inner seat & upholstery to assist work load | New | | 150.00 |
| | | | 2,350 | |
| | | Gross Labour Cost (S$) | | 3,610.00 |

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

**< END OF ESTIMATES >**

15,446.30
− 25%
P : 11,584.73
L : 2,350
13,934.73
− 20%
11,147.78

21 S
$11,150
7 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: