ASS. REC. BY: Steve | CC4/GRB2202 8864/P93

# ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

| N/S | O/S |
|---|---|
| | |

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKZ 2786L Yr Regn: 14/1/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toyota Harrier c.c 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 83306 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2SU6000 67711

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/65R16

R: ,,

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Randtrek

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 4 mm | R/Bal. | 4 mm |
| L/Bal. | 4 mm | L/Bal. | 4 mm |
| D.O.A. | 18/8/22 | D.O.I. | 13/9/22 |

Survey held at Mara

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | MV-74K |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Repair Format : _____

Lump Sum / I.B.I: ($ _____)

| | |
|---|---|
| Survey Fee: | |
| Transportation: ___$ + RS.___SI | |
| Photos | |
| Others | |
| TOTAL | |

CamScanner

MOVA Automotive Pte Ltd

**Main Office :** No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 1008, Bukit Merah Lane 3, #01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0086864-2

**Mova Spray Centre**
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**
Specialise In Car Air-con Services, Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**
**Hilton Auto Trading**
Dealing In New/Used Cars, Hire Purchase & Insurance.

**TP INSURER:** **India International Insurance Pte Ltd (HQ)**
**UNKNOWN**

Singapore

## PARTICULARS OF CLAIM

| | | | |
|---|---|---|---|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 18/08/2022 |
| Vehicle Reg. No.: | **SKZ2286L** | Driveable? | |
| Party At Fault: | UNKNOWN | | |
| Make/Model: | TOYOTA HARRIER, 2.0 (A) | Vehicle Reg. Date: | 14/01/2016 |
| Vehicle Colour: | BLACK | | |
| Engine No: | 3ZRB691446 | Chassis No: | ZSU600067711 |
| Odometer: | 0 KM | | |
| Paint Type: | | | |
| List Item Discount: | 25.00 % | | |
| Total Loss? | **NO** | | |
| Est. Duration of Repair (day) | 7 | | |
| Present Location: | MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) | | |

## COST OF CLAIMS

| | Amount |
|---|---|
| Parts | 7,283.25 |
| Miscellaneous Items | 11.00 |
| Labour | 3,170.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S$) | **10,464.25** |
| + GST 7.00% (S$) | 732.50 |
| Nett Amount (S$) | **11,196.75** |

**This claim is handled by: PATRICK**

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***



CamScanner

## AIR DETAILS

### erence

| | | |
|---|---|---|
| A Source: | MRM-SG | Version: 1.0 (Last Synchronised: 23 Aug 2022) |
| arts: | M1-SUV | TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKZ2286L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

## Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|---|---|---|---|---|---|---|
| 1 | 1 | | *FRONT RH FENDER X R | 25.00 | 0.00 | *1,447.00 FL |
| 2 | 1 | | *FRONT RH DOOR CHROME PROTECTOR X | 25.00 | 0.00 | *159.00 FL |
| 3 | 1 | | *FRONT RH DOOR OUTER CHROME HANDLE X | 25.00 | 0.00 | *474.00 FL |
| 4 | 1 | | *FRONT RH DOOR OUTER CHROME KEY COVER X | 25.00 | 0.00 | *56.00 FL |
| 5 | 1 | | *RH WING MIRROR MOTOR HOUSING X | 25.00 | 0.00 | *1,357.00 FL |
| 6 | 1 | | *REAR RH DOOR / DO | 25.00 | 0.00 | *1,581.00 FL |
| 7 | 1 | | *REAR RH DOOR OUTER CHROME PROTECTOR – CM | 25.00 | 0.00 | *159.00 FL |
| 8 | 1 | | *UREAR RH DOOR WEATHERSTRIP X | 25.00 | 0.00 | *193.00 FL |
| 9 | 1 | | *REAR RH DOOR GLASS OUTER MOULDING X | 25.00 | 0.00 | *159.00 FL |
| 10 | 1 | | *REAR RH DOOR FRAME BLACK STICKER (TOP) / M | 25.00 | 0.00 | *58.00 FL |
| 11 | 1 | | *REAR RH DOOR FRAME BLACK STICKER (REAR VERTICAL) – M | 25.00 | 0.00 | *49.00 FL |
| 12 | 1 | | *REAR RH ALLOY RIM 17 – CM | 25.00 | 0.00 | *2,312.00 FL |
| 13 | 1 | | *REAR RH FENDER X R | 25.00 | 0.00 | *1,707.00 FL |

F=Franchise part. L=ListItemDisc.

| | |
|---|---|
| Sub Total (S$) | 9,711.00 |
| - List Item Discount on L Items (S$) | 2,427.75 |
| Total Parts (S$) | 7,283.25 |

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**



CamScanner

## Estimates on Miscellaneous Items

| Qty | Particulars | | Amount |
|---|---|---|---|
| **Miscellaneous Items** | | | |
| 1 | OD/TP Case (Insurer) | nec | 11.00 |
| | | Sub Total (S$) | 11.00 |

## Estimates on Labour

| No | Particulars | Lab.Type | | Amount |
|---|---|---|---|---|
| **Labour Items** | | | | |
| 1 | TO CUT WELD RH REAR FENDER , JACK STRAIGHTEN ON AFFECTED AREA, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS | New | 500 | 1,100.00 |
| 2 | TO PATTY, RESPARY ON RH FRONT FENDER, RH WING MIRROR, RH FRONT DOOR, RH REAR DOOR, RH REAR FENDER, REAR BUMPER RH REAR RIM & AFFECTED AREAS | New | 1000 | 1,500.00 |
| 3 | TRANSFER RH REAR DOOR PARTS TO NEW DOOR | New | 50 | 100.00 |
| 4 | CHECK WHEEL ALIGNMENT | New | | 80.00 |
| 5 | TO TUFF KOTE ON AFFECTED AREAS | New | 30 | 120.00 |
| 6 | TO REMOVE & REPLACE RH REAR WHEEL RIM & BALANCING | New | 30 | 50.00 |
| 7 | CHECK LIGHTING & WIRING | New | 30 | 60.00 |
| 8 | TO REMOVE INTERIOR UPHOLSTERY TO REPAIR & REFIT | New | X | 160.00 |
| | | Gross Labour Cost (S$) | | 3,170.00 |

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Steve (LKK)
13/9/22 4.30pm
m R
L/S
hy M y
S dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



CamScanner