LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIS22009711/EPA3Q2
Date: 07/12/2022

REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPMF1000000502	
Claimant Vehicle No :	SMF4491D	**Insured Vehicle No :**	SMG2023E	
Date of Loss:	29/09/2022	Nature of Claim:	TP	Claim No: CARAISCL2022-00013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SMF4491D**		
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 HIGHLINE 280 TSI (A)	Engine No:	CZE811509
Reg. Date:	12/11/2018 (Man. Year: 2018)	Chassis No:	WVGZZZ5NZJW964010
Colour:	Grey	Odometer:	51891 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R16	Rear Tyre Size:	225/60 R16
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,006.89	5,294.74	1,712.15	24.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	2,940.00	2,120.00	41.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**12,066.89**	**8,234.74**	**3,832.15**	**31.76**
+ GST 7.00/7.00% (S$)	844.68	576.43	268.25	31.76
Nett Amount (S$)	**12,911.57**	**8,811.17**	**4,100.40**	**31.76**
+ Loss of Use (4.0 x S$60.00/day) (S$)		240.00		
+ Doc/Search Fee (S$)		7.45		
Nett Liability (S$)		**9,058.62**		

INSPECTION

Date of Assignment:	05/10/2022		
Date Inspected:	05/10/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE **Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 HIGHLINE 280 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF4491D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***COVER FOR BUMPER PRIMED**	Dented	1,459.22 FS	*1,459.22 FS
2	1		***SPOILER SATIN BLACK**	Not Necessary	341.54 FS	*- FS
3	1		***SET LICENSE PLATE BRACKET**	Crushed	90.76 FS	*90.76 FS
4	5		***RIVET**	Not Necessary	1.98 FS	*- FS
5	1		***GUIDE PIECE LHS BUMPER SIDE BRACKET**	Not Necessary	24.04 FS	*- FS
6	1		***GUIDE PIECE RHS BUMPER SIDE BRACKET**	Not Necessary	24.04 FS	*- FS
7	1		***BUMPER REINFORCEMENT**	Not Necessary	816.44 FS	*- FS
8	1		***FOAM INSERT**	Not Necessary	63.03 FS	*- FS
9	1		***EXPANDING NUT** (4 PCS)	Necessary	8.71 FS	*8.71 FS
10	1		***UNDERRUN BAR GRANITE GREY**	Broken	345.13 FS	*345.13 FS
11	1		***RADIATOR GRILLE COMPLETE**	Broken	508.70 FS	*508.70 FS
12	1		***VW SIGN HIGH CHROME /BLACK**	Not Necessary	308.81 FS	*- FS
13	1		***COOLING AIR GRILL SATIN B BUMPER CTR LOWER GRILLE**	Broken	193.83 FS	*193.83 FS
14	1		***DECORATIVE MOULDING CHROM BUMPER CTR LOWER GRILLE CHROM**	Broken	148.16 FS	*148.16 FS
15	1		***COOLING AIR GRILL SATIN B BUMPER LOWER GRILLE LH**	Not Necessary	67.83 FS	*- FS
16	1		***TRIM SATIN BLACK LHS FOG LAMP TRIM**	Not Necessary	45.05 FS	*- FS
17	1		***GUIDE BUMPER CTR BRACKET**	Broken	65.86 FS	*65.86 FS
18	1		***LED HEADLIGHT LHS H/LAMP**	Broken	2,167.61 FS	*2,167.61 FS
19	1		***FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING**	Not Necessary	19.39 FS	*- FS
20	1		***FRT NUMBER PLATE**	Cut	80.00 FS	*80.00 FS
21	1		***SENSOR BRACKET PRIMED**	Necessary	15.90 FS	*15.90 FS
22	1		***SENSOR BRACKET PRIMED**	Necessary	15.90 FS	*15.90 FS
23	1		***2K-PLASTIC ADHESIVE**	Necessary	77.35 FS	*77.35 FS
24	1		***BONDING AGENT FOR PLASTIC**	Necessary	61.97 FS	*61.97 FS
25	1		***STICKER AC REFRIGERAN**	Necessary	16.98 FS	*16.98 FS
26	1		***STICKER OIL COMPLY WITH**	Necessary	23.87 FS	*23.87 FS
27	1		***STICKER OVERFILLED ENGIN**	Necessary	14.79 FS	*14.79 FS

F=Franchise part. S=SpcNett.

Total Parts (S$)	**7,006.89**	**5,294.74**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**LABOUR**	New	2,160.00	720.00
2	**SPRAY PAINT**	New	2,040.00	1,360.00
3	**B&P CHECK SHORT CIRCUIT /HARNESS REPAIR**	New	280.00	280.00
4	**B&P DIAGNOSIS AND PROGRAMMING**	New	480.00	480.00
5	**TO ALIGN LED HEADLIGHT**	New	100.00	100.00
	Gross Labour Cost (S$)		**5,060.00**	**2,940.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >