LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items [illegible] and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717
Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Quotation

DATE : 02.11.2022
VEH NO : SJM9222E
MODEL : Honda Freed
D O A : 27.10.2022
YR REF : SLU5988P

GB31025672

AIG ASIA PACIFIC INSURANCE PTE LTD
Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Xiao Tong

2028 Dec.

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

PE : ESTIMATE FOR ACCIDENT REPAIR SJM9222E (HONDA FREED)

Item NO	Description LIST ITEMS		Qty	Amt
1	Rear Number Plate Lamp - LH & RH	Not new	2	97.00 X.
2	Rear Bumper	Dented	1	845.10
3	Rear Bumper Side Holder - LH & RH	Dmgd	2	77.00
4	Rear Bumper Tow Cover	Dented.	1	35.20
5	Rear End Panel	Distorted.	1	645.10
6	Rear End Panel Top Garnish	Dented.	1	228.30
7	Tailgate	Distorted	1	1,288.10
8	Tailgate Lock	Dmgd	1	282.90
9	Tailgate Inner Holder	Cracked.	1	55.90
10	Tailgate Weatherstripe	Cut	1	225.40
11	Tailgate Outer Garnish	Dmgd	1	287.30
12	Tailgate Inner Trim Board	Dented	1	366.40
13	Tailgate Wiper Motor	Not new	1	385.40 X.
14	Tailgate Glass Moulding	New	1	158.40
15	Honda Logo	New	1	55.40
16	Freed Wording	New	1	68.70
17	Sports Wording	New	1	50.40
18	RS Emblem	New	1	65.90
19	VTEC Emblem	New	1	64.20
20	Turbo Emblem	New	1	55.10
21	Taillamp - LH & RH	LH cracked	2	~~760.40~~ 380.20.
22	Floor Panel	Repair	1	1,450.90 X.
23	Floor Panel Top Carpet	Not new	1	337.20 X.
24	Rear Fender Inner Trim Board - LH & RH	LH Dented	2	~~910.20~~ 455.10.
25	Rear Exhaust Pipe	Not new	1	662.50 X
26	Rear Exhaust Pipe Mounting	Not new	1	38.50 X
27	Rear Exhaust Pipe Gasket	Not new	1	34.60 X.

RE : ESTIMATE FOR ACCIDENT REPAIR SJM9222E (HONDA FREED)

		5690.10		9,531.50
	Less 20%	4552.08		(1,906.30)
			$	7,625.20

S/NETT ITEMS

1	Rear Number Plate	Dented	1	$	30.00
2	Rear Number Plate Holder		1	$	30.00
3	Rear Bumper Clips	New	1 set	$	30.00
4	Reverse Sensor	Damaged	1	$	~~280.00~~ 200.
5	Rear End Panel Top Garnish Clips	New	1 set	$	~~20.00~~
6	Rear End Panel Sealant	New	1	$	60.00
7	Tailgate Inner Trim Board Clips	New	1 set	$	30.00
8	Tailgate Surround Lining (Red)	New	1	$	~~250.00~~ 150.
9	Tailgate Glass Sealant	New	1	$	60.00
10	Tailgate Sticker (Black)		1	$	~~150.00~~ 80.
11	Tailgate Top Spoiler	New	1300 1	$	1,500.00 X.
12	Rear Camera	Damaged.	1	$	~~480.00~~ 380.
13	Floor Panel Sealant	New	1	$	60.00 X.
14	Floor Panel Insulation Pad	New	1	$	~~250.00~~ 200
15	Rear Fender Inner Trim Board Clips	New.	1 set	$	~~60.00~~ 30
		Total Parts		$	10,915.20

LABOUR CHARGE

1	To knocking & pull out rear door portion & renew above parts		$	~~1,600.00~~ 1000
2	To putty & spray up paint works		$	~~1,500.00~~ 800.
3	To check wiring		$	~~100.00~~ 30
4	To spray tuff coat	2390	$	~~150.00~~ 80
5	To remove reverse sensor		$	~~100.00~~ 50
6	To remove rear camera		$	~~100.00~~ 50
7	To remove upholstery		$	~~150.00~~ 80.
8	To remove tailgate glass		$	~~180.00~~ 120
9	To transfer tailgate fittings		$	~~150.00~~ 80
10	To remove exhaust pipe		$	150.00 X.
		Total Labour	$	4,180.00

total: 8242.08
c/s: 6.6K.
07 Days.