BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 24-Jun-22 INSURANCE: _____

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 7918 X

Description	Qty	List Price	Amount	
Bonnet HN	1	$ 2,253.80	$ 2,253.80	X
Bonnet Hinge (LH/RH) HN	2	$ 118.70	$ 237.40	X
Bonnet Moulding HN	1	$ 41.40	$ 41.40	X
Bonnet Lock SVL	1	$ 127.30	$ 127.30	X
Bonnet Insulator HN	1	$ 230.10	$ 230.10	X
Bonnet Insulator Clips HN	1	$ 15.00	$ 15.00	X
Radiator Grille NEW MODEL CW	1	$ 1,568.60	$ 1,568.60	✓
Flap Assy Active Air Upper, (LH/RH) minority crack	2	$ 824.60	$ 1,649.20	✓
Speaker Assy-VESS HN	1	$ 554.40	$ 554.40	X
Front Number Plate garnish SVL	1	$ 188.00	$ 188.00	X
Front Bumper Cover torn	1	$ 481.10	$ 481.10	✓
Front bumper top cover ~~TOP~~ SVL	1	$ 476.30	$ 476.30	X
Front Bumper Sponge torn	1	$ 186.90	$ 186.90	✓
Front Bumper Reinforcement Dent	1	$ 1,136.70	$ 1,136.70	✓
Front Bumper Reinforcement ABSORBER (LH/RH) O/S St	2	$ 186.50	$ 373.00	✓
Front Bumper Towing Cover SVL H/S HN	1	$ 29.00	$ 29.00	X
Front Bumper Moulding Centre Upper deformed / distorted	1	$ 368.50	$ 368.50	✓
Front Bumper Moulding HN	1	$ 93.60	$ 93.60	X
Front Bumper Lower Stiffner HN	1	$ 285.10	$ 285.10	X
Front bumper lower grille deformed / distorted	1	$ 365.30	$ 365.30	✓
front bumper lower grille moulding St	1	$ 127.60	$ 127.60	✓
Front Bumper Lip HN	1	$ 35.10	$ 35.10	X
Front Bumper Bracket Top (LH/RH) broken	2	$ 35.00	$ 70.00	✓
Front Bumper Bracket (LH/RH) O/S broken H/S NN	2	$ 28.00	$ 56.00	✓
Front Bumper Retainer Mounting (LH/RH) HN	2	$ 65.30	$ 130.60	X
Front Bumper Clips 10 pcs HC	1	$ 25.00	$ 25.00	✓
Front Bumper Grille (LH/RH) SVL	2	$ 186.90	$ 373.80	X
Front bumper air duct (LH/RH) HN	2	$ 153.80	$ 307.60	X
Day Light ,LH HN	1	$ 642.50	$ 642.50	X
Day Light , RH minority broken	1	$ 642.50	$ 642.50	✓
Headlamp Support Panel Assy crack minority broken	1	$ 1,139.30	$ 1,139.30	✓
Headlamp(LH/RH) crack / minority broken	2	$ 3,987.30	$ 7,974.60	✓
Horn Unit (LH/RH) HN	2	$ 72.80	$ 145.60	X
Radiator Inverter St	1	$ 884.80	$ 884.80	✓
Radiator St	1	$ 710.50	$ 710.50	✓
Radiator fan blower motor assy crack	1	$ 1,459.60	$ 1,459.60	✓
Radiator Air Guard (LH/RH) HN	2	$ 76.40	$ 152.80	X
Aircon Condenser St	1	$ 663.60	$ 663.60	✓
SUB TOTAL			**$ 26,202.20**	
LESS 20%			**$ 5,240.44**	
DISCOUNTED TOTAL			**$ 20,961.76**	

Front Number Plate	SN	1	$ 25.00	$ 25.00	
Front No Plate Trim Cover	SN	1	$ 30.00	$ 30.00	
COOLANT	SN	1	$ 45.00	$ 45.00	
Emblem-Blue Drive (LH/RH)	SN	2	$ 26.60	$ 53.20	
SUB TOTAL				**$ 153.20**	
Labour Charge					
Panel Beating		1	$1,600.00	~~$1,600.00~~	700/-
Spray Painting Charge		1	$1,400.00	~~$1,400.00~~	500/-
Wiring Charge		1	$100.00	~~$100.00~~	30/-
Tuff Kote		1	$100.00	~~$100.00~~	40/-
Towing Charge		1	$80.00	$80.00	NH
Remove/Refix Radiator		1	$90.00	~~$90.00~~	50/-
Remove/Refix Aircon & Refill Gas		1	$130.00	~~$130.00~~	80/-
Diagnostic & Resetting To Erase Fault Code		1	$550.00	~~$550.00~~	150/-
TOTAL LABOUR				**$4,050.00**	
ESTIMATE TOTAL				**$25,164.96**	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

27/06/2022 @ 1030hrs

5 days.

JKK Auto Check pm plus.