# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

STRIDES AUTOMOTIVE SERVICES PTE LTD

60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: CS3/SMR22011155/Sqy3m4
Date: 23/12/2022
Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 5752A	Veh. Inspected	JQS 6627
Policy No.		Coverage ($)	0.00
Claim No.	TAX/11/22/2005	Excess ($)	0.00
Assign From	HUA YEN	Assign Date	08/11/2022

2. Vehicle Particulars & Condition

Make & Model	YAMAHA 115ZRI	c.c	115
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	PMYUE0740E0041874	Colour	WHITE
Odometer	48492 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S & N/S BODY.

5. General Information

Accident Date	03/11/2022	Inspect Date / Time	23/11/2022 (03:30 PM)
Survey held at	EQBH PTE LTD 25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $1,500-$2,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/SMR22011155/Sqy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser