Elite Automotive Pte Ltd (Co.Reg.No:201700196D)
280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands
Singapore 757322
Tel: 9388 2885/8136 4741/63397378 Fax: 63397475 Email: elite.automotive13@gmail.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2003362215-01	Date of Loss:	23/12/2022
Vehicle Reg. No.:	**SML6475G**	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEIXIANG HENRY ANG	Contact No:	+6594888486
Driver:	WEIXIANG HENRY ANG		
Make/Model:	HONDA FREED HYBRID, 1.5 (A)	Vehicle Reg. Date:	29/05/2019
Vehicle Colour:	Blue		
Engine No:	LEB5625468	Chassis No:	GB71087435
Odometer:	53782 KM		
Paint Type:			
Total Loss?	**NO**		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	PLEASE REFER TO		
Present Location:	ELITE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	11,426.80
Miscellaneous Items	60.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S$)	**15,866.80**
- Excess (S$)	600.00
(S$)	15,266.80
+ GST 7.00% (S$)	1,068.68
Nett Amount (S$)	**16,335.48**

This claim is handled by: HANG PEK CHIN

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	**Elite Automotive Pte Ltd/SML6475G/28/12/2022 14:36**	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		***BONNET**	0.00	0.00	*580.00 F
2	2		***BONNET HINGES (LH & RH)**	0.00	0.00	*100.00 F
3	1		***BONNET INSULATION**	0.00	0.00	*80.00 F
4	10		***BONNET INSULATION CLIPS**	0.00	0.00	*30.00 F
5	1		***BONNET STAND**	0.00	0.00	*35.00 F
6	1		***BONNET STAND CLIP**	0.00	0.00	*5.00 F
7	1		***BONNET LOCK**	0.00	0.00	*120.00 F
8	1		***FRONT BUMPER**	0.00	0.00	*700.00 F
9	2		***FRONT BUMPER RETAINER (LH & RH)**	0.00	0.00	*40.00 F
10	10		***FRONT BUMPER CLIPS**	0.00	0.00	*30.00 F
11	1		***FRONT BUMPER REINFORCEMENT**	0.00	0.00	*380.00 F
12	1		***FRONT BUMPER LOWER GRILLE**	0.00	0.00	*160.00 F
13	1		***TOWING CAP**	0.00	0.00	*18.00 F
14	1		***FRONT GRILLE**	0.00	0.00	*680.00 F
15	2		***HEADLAMP (LH & RH)**	0.00	0.00	*2,400.00 F
16	2		***HEADLAMP LOWER BRACKET (LH & RH)**	0.00	0.00	*80.00 F
17	2		***FRONT FENDER (LH & RH)**	0.00	0.00	*800.00 F
18	1		***AIRCON CONDENSER**	0.00	0.00	*850.00 F
19	1		***RADIATOR**	0.00	0.00	*980.00 F
20	2		***FAN COWLING**	0.00	0.00	*240.00 F
21	2		***FAN MOTOR**	0.00	0.00	*560.00 F
22	2		***FAN BLADE**	0.00	0.00	*160.00 F
23	1		***A/C SUCTION PIPE**	0.00	0.00	*220.00 F
24	1		***A/C DISCHARGE PIPE**	0.00	0.00	*260.00 F
25	1		***A/C LIQUID PIPE**	0.00	0.00	*280.00 F
26	1		***SUPPORT PANEL**	0.00	0.00	*600.00 F

F=Franchise part.

Sub Total (S$)	**10,388.00**
+ Margin on L,N Items 10.00% (S$)	1,038.80
Total Parts (S$)	**11,426.80**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	**FRONT NUMBER PLATE WITH HOLDER**	60.00
		Sub Total (S$)	**60.00**

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	**LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.**	New	1,800.00
2	**TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT BOTH FENDER, SUPPORT PANEL, FRONT BOTH A PILLAR**	New	1,800.00
3	**TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.**	New	280.00
4	**TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS, TO VACUMM & CHARGE UP GAS.**	New	150.00
5	**TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.**	New	200.00
6	**TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIR. INCLUDING PRESSURIZE COOLING SYSTEM.**	New	150.00
		Gross Labour Cost (S$)	**4,380.00**

Elite Automotive Pte Ltd/SML6475G/28/12/2022 14:36. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >