# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AUTO & GENERAL INSURANCE (S) PL	Ref:	CS3/AGI23001356/Kqy3e2
(BUDGET DIRECT INSURANCE)190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Date:	13/02/2023
	Code:	AGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKQ 5755C	**Veh. Inspected**	SLC 6952E
Policy No.		**Coverage ($)**	0.00
Claim No.	C10020315 /CD	**Excess ($)**	0.00
Assign From	FRAULEINE KHOO	**Assign Date**	08/02/2023

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	**c.c**	1496
Engine No.	HIDDEN	**Year of Reg.**	2016
Chassis No.	JM6BM42A8G0334474	**Colour**	METALLIC BLACK
Odometer	199655 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	9 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	9 mm
R/H Rear Tyre	205/60 R16	WINDFORCE	9 mm
L/H Rear Tyre	205/60 R16	WINDFORCE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

5. General Information

Accident Date	02/02/2023	**Inspect Date / Time**	09/02/2023 (10:02 AM)
Survey held at	GOH LEE HWA AUTOMOBILE PTE LTD		
	BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,000-$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

Report Ref No. CS3/AGI23001356/Kqy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser