LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : GBA 4022 G
MAKE : TOYOTA
MODEL : HIACE MANUAL
YEAR : 2007
CHASSIS NO : JTFHT02P600004453

DATE : 15-Feb-23
DATE OF ACCIDENT : 14-Feb-23
THIRD PARTY REF PC 63 M
THIRD PARTY REF CHINA TAIPING INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper				$ 481.80
2 pc	Rear bumper retainer		$ 24.80		$ 49.60
1 pc	Rear end panel				$ 363.70
1 pc	Rear end panel garnish				$ 112.30
1 pc	Tail gate				$ 2,293.20
1 pc	Tail gate outer garnish				$ 151.20
1 pc	Tail gate Emblem				$ 72.20
1 pc	Tail gate lock				$ 293.50
1 pc	Tail gate rubber				$ 433.30
					$ 4,250.80
	Less 25%				$ 1,062.70
					$ 3,188.10
1 pc	70km/h sticker	S/N			$ 15.00
1 pc	Dangerous highly flammable sticker	S/N			$ 80.00
1 pc	Flammable liquid sticker	S/N			$ 40.00
1 pc	Rear No plate	S/N			$ 40.00
	To putty & spray paint				$ 500.00
	To transfer tail gate fitting				$ 80.00
	Labour charge				$ 600.00
TG/ZX	TOTAL				$ 4,543.10

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg