LKK Auto Consultants Pte Ltd
Company Registration No. 199607198R
51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 23.30489 Date: 04th April 2023

Our Ref: CS3/ASM22007533/Tnp3m4-1

M/s HSBC Life (Singapore) Pte Ltd
C/o Seah Ong & Partners LLP
36 Robinson Road #12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBJ 9852Y
INSURED VEHICLE: SJN 2524A
ACCIDENT DATE: 31/07/2022

We thank you for your instruction on 08/03/2023.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of FBJ 9852Y from Lee Appraisal Services.
b) Singapore Accident Statement of Vehicles FBJ 9852Y and SJN 2524A.
c) Police Report of Vehicles FBJ 9852Y and SJN 2524A.
d) Final Repair Bill of FBJ 9852Yfrom M/s Speedy Motor Cycle Service Centre.
e) Colour damaged vehicle photographs of FBJ 9852Y.

Pre-Repair Inspection Date: 10/08/2022 at M/s Speedy Motor Cycle Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A #05-21, Singapore 568047.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBJ 9852Y
Make & Model	: Kymco K-XCT200I
Year of Registration	: 2015
Chassis Number	: RFBD82000F1000198
Engine Capacity	: 199 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.