Surveyor

REF: CS4/MSG23002729/P qy3

ASSIGNMENT

From: Sherwin Date: 21/4/2023

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: SUZUKI BURGMAN 200 ABS

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBK 2806Y Yr Regn: May / 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Suzuki Burgman. ABS. c.c 200

Colour A/C: Insured / Std / NI / NA

Sp.Reading T/Radio: Insured / Std / NI / NA

Eng/No: H405402163

C/No: MLCC9112100402163.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: —

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or —

Front		Rear	
R/Bal.	— mm	R/Bal.	— mm
L/Bal.	— mm	L/Bal.	— mm

D.O.A. 16/March 2023 D.O.I. 11/March 2023.

Survey held at Glen Enterprise Pte Ltd.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Whole motorcycle burnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - $3,800
	Part - $1,396
	NL = $2,404
21/04/23	Submit Ectensive Total Loss report.
	Investigation billing charge $500/-

Date/Time, File Pass to? [ ] : Preli. Report

21/04 Typist [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: [ ] : Site Insp ($) S + RS SI

[ ] : Interview ($) Photos

[ ] : Tech. Invs ($) Others

[ ] : Weekend ($)

Report Format : MER-OD/TL-E

Lump Sum / I.B.I: ($)

TOTAL